





Metro Portland'5 Centers for the Arts

Facility Condition Assessment for
Antoinette Hatfield Hall

April 10, 2026 | Prepared by: Sazän Group

Contents

1. Building Executive Summary	1
1.1. Purpose and Scope of the Assessment.....	2
1.2. Facility Summary Information	2
1.3. Key Findings and Recommendations	3
1.4. Summary of Total Estimated Costs	5
2. Methodology.....	8
2.1. Facility Condition Assessment.....	9
2.2. Corrective Action Categories	9
2.3. Condition Rating Overview	11
2.4. Cost Estimating Assumptions.....	12
3. Building Summary.....	16
3.1. Facility Overview.....	17
3.2. Condition Assessment.....	17
3.3. Corrective Action Summary	20
3.4. List of Corrective Actions	21
3.5. Facility Conditions.....	73
3.6. Asset Inventory and Asset Condition Ratings.....	76
3.7. Prioritized 5-Year List of Corrective Actions	78
3.8. Prioritized 6–10 Year List of Predicted Renewals.....	80
3.9. Estimated 10–20 Year Maintenance and Recapitalization Need.....	81
3.10. Estimated 20–30 Year Maintenance and Recapitalization Need.....	83
3.11. Recommendations for Follow-up Assessments	83
4. How to use this Report.....	85
5. Appendices.....	87

1. Building Executive Summary

1.1. Purpose and Scope of the Assessment

On November 18, 2025, Săzăn Group (Săzăn) conducted a Facility Condition Assessment (FCA) of three Portland's Centers for the Arts facilities, including Antoinette Hatfield Hall (AHH). The purpose of this FCA was to provide a comprehensive evaluation of the physical conditions of building systems and provide short, medium, and long-term cost projections of the facility. The assessment was performed to support Metro's asset management objectives, including establishing a consistent baseline of asset condition data, identifying major maintenance needs, and short-to-mid-term capital planning.

The FCA included rapid visual assessments of building and site systems, engagement with facility stakeholders and staff, and the development of a structured asset inventory consistent with Metro's asset classification hierarchy and data standards. Major building systems were evaluated, including architectural, structural, mechanical, electrical, plumbing, civil, life-safety, and specialized theater systems. No destructive testing was conducted that might otherwise indicate further condition issues. Each asset was evaluated at Unifomat Level 4, using Metro's asset classification hierarchy, which is based on Unifomat but incorporates agency-specific numbering that does not always directly correspond to standard Unifomat designations. Assets were assigned condition ratings, estimated remaining useful life, replacement costs, and criticality to facility operations.

The scope of work also included identification of potential statutory, regulatory, and code deficiencies; assessment of operational and maintenance practices; evaluation of risk of failure and consequence of failure for critical assets; and development of prioritized recommendations for repair, rehabilitation, and capital replacement.

1.2. Facility Summary Information

Constructed in 1987, AHH is nearly 40 years old. The building structure appears to have sound structural integrity and is well maintained, though no longer meets current seismic codes and shows normal wear and tear. Original building construction employed quality building systems and finish materials, and the building appears capable of exceeding the planned 50-year building life. While many systems are near or have exceeded normal useful life, positive maintenance practices have enabled the avoidance of major building system failures.

Over the past decade several critical building systems have been rehabilitated or replaced, including the primary roof system (2018), fire alarm system (2018), largest air handling unit (2025), and both stage door and passenger elevators (2025). The facility is currently due for major capital renewal, particularly the building envelope systems. The building's complex exterior modulation creates numerous transition points, increasing vulnerability at material interfaces and across the various roof and wall enclosure assemblies.

1.3. Key Findings and Recommendations

Theater Systems

1. Existing manual and motorized stage rigging equipment are well maintained but have exceeded manufacturer's recommended operational life rating.
Recommendation: Replace aging stage rigging components, evaluate the supporting structure, and have the systems inspected and certified by a qualified contractor.
2. Existing motorized orchestra pit and seating lifts in Newmark and Winningstad have likely exceeded their manufacturer's recommended useful life.
Recommendation: Conduct a comprehensive inspection and servicing of the lifts and plan for full replacement as they reach the end of their useful life.
3. Most stage lighting fixtures are older technology that is still functional but relies on lamps that are becoming harder to obtain as the industry moves to newer systems. Over time, this may impact reliability and operating costs, and transitioning to modern lighting will require a significant capital investment.
Recommendation: Develop a phased capital plan to transition to modern lighting systems before existing lamps become difficult to obtain, improving reliability and managing long-term costs.

Architectural Systems

4. Front-of-house interior finishes are original to the building and have exceeded their typical service life, though they have been well maintained. Visible wear, including discolored and frayed carpet, aging millwork panels, deteriorating banquet seating, cracked and loose stone-topped built-in cocktail tables, worn restroom partitions, and water-damaged column finishes, indicates that coordinated replacement will be needed in the near future.
Recommendation: Develop a phased program to renew front-of-house interior finishes to address visible wear and extend their useful life, maintaining the building's appearance and overall visitor experience.
5. Back-of-house spaces have been well maintained; however, many interior components are original and are reaching the end of their useful life. Aging carpet, outdated door hardware, and water damage to finishes along exterior walls indicate that targeted renewal will be needed.
Recommendation: Implement a phased renewal program for back-of-house interiors to replace aging finishes and hardware and address water-damaged areas, helping maintain building functionality.

Structural Systems

6. Structural systems are generally in good condition, but localized concrete degradation at exterior columns due to water exposure requires targeted repair and monitoring.
Recommendation: Have a qualified structural professional evaluate the affected columns, repair damaged concrete, and correct the source of water intrusion to prevent further deterioration.

7. The building's floor slabs are generally in good condition, but localized uneven settlement has been observed in a front-of-house ground floor lobby area.
Recommendation: Investigate the cause and extent of settlement in the lobby slab and complete appropriate repairs to restore a stable, level surface.

Building Envelope Systems

8. Systemic water intrusion and moisture management deficiencies were observed in many locations throughout the building exterior and interior systems. Evidence of these issues is widespread and appears on exterior columns, exterior windows, roofing, roof penetrations, gutters and downspouts, and interior wall and column finishes. Active and recurring leaks, failed sealants, poor drainage configurations, and organic growth in drainage components have contributed to widespread moisture-related deterioration, has resulted in accelerated failure of exterior finishes and likely to substrates.
Recommendation: Implement a comprehensive building envelope remediation program, including replacement of failed sealants, correction of curtain wall drainage deficiencies, targeted masonry repairs and repointing, roof replacement, and repair of roof penetrations and interfaces to eliminate active and recurring water intrusion and prevent continued interior deterioration.
9. Exterior building envelope components are deteriorating, with cracked brick masonry, mortar joints nearing end of life, compromised insulated glass units, and sealants at or beyond end of useful life.
Recommendation: Implement a comprehensive building envelope remediation program, including targeted masonry repairs targeted structural repairs.
10. Roofing systems that were not replaced in 2018 are in poor condition, with the Brunish flat roof requiring replacement and multiple leak paths identified at roof openings and interfaces.
Recommendation: Replace affected roofing areas.

Mechanical Systems

11. The building automation system is approaching the end of its expected service life, including controllers, sensors, and wiring.
Recommendation: Replace with new.
12. Several air handling units that provide heating and cooling throughout the building are nearing the end of their expected service life.
Recommendation: Replace worn fan motors, upgrade to more efficient variable speed systems, and service internal components to extend equipment life.
13. The building's chiller, installed around 1999, is nearing the end of its expected service life.
Recommendation: Begin planning for a chiller replacement.
14. The cooling tower and chemical treatment system are approaching the end of their expected service life.
Recommendation: Begin planning for a cooling tower replacement in conjunction with the chiller replacement.

Electrical Systems

15. Overall electrical system performance appears stable under current operating conditions.
16. Main electrical distribution equipment, sub distribution panels, and emergency power components are original (1987) and past their useful life.

Recommendation: Develop a capital renewal plan for aging electrical distribution equipment.

1.4. Summary of Total Estimated Costs

Based on observed conditions, maintenance practices, age of building systems and remaining useful life, the FCA developed order-of-magnitude (ROM) cost estimates for required repairs, rehabilitation, and capital replacements. Costs are presented in current dollars and represent planning-level estimates (i.e., +/- 30%) intended to support planning, budgeting and prioritization.

This FCA report identifies that AHH has approximately \$10M-\$17.5M in immediate and priority building system costs recommended for planned budgeting of replacement or repair at AHH in the next five years. These high costs are not unusual for a 40-year-old building that supports high public use. Given the primary use of AHH relates to supporting the functions of three production theaters, it is not surprising to find that 47% of these projected costs are related to the specialized theater related systems. The following tables and graphs summarize the total expenditures and corrective actions broken down by discipline.

[This portion of the page left intentionally blank so that the following charts and tables appear in a single page]

Total Expenditures




Figure 1. Total Recapitalization Need

Cost Category	Planning-Level Cost Range*
Immediate / High Priority (2026–2030)	\$10M-\$17.5M
Short Term (2031–2035)	\$37M-\$69M
Mid Term (2036–2045)	\$27M-\$50M
Long Term (2046–2055)	\$0
Total Estimated Capital Need	\$74M-\$136.5M

Table 1. Total Recapitalization Need

*Planning-level cost ranges reflect typical order-of-magnitude accuracy for Facility Condition Assessments.

Immediate / High Priority (2026-2030) Costs by Discipline

Theater Systems	\$5.0M–\$8.0M
Architectural Systems	\$1.0M–\$2.0M
Structural Systems	\$0.0M–\$0.5M
Building Envelope Systems	\$2.0M–\$3.0M
Mechanical Systems	\$1.5M–\$2.5M
Electrical Systems	\$0.5M–\$1.5M
TOTAL	\$10.0M–\$17.5M

Table 2. Total Corrective Action Costs by Discipline




Figure 2. Total Corrective Action Costs by Discipline

2. Methodology

2.1. Facility Condition Assessment

Metro engaged S&B to perform a Facility Condition Assessment (FCA) for AHH. The FCA was conducted as a high-level observational assessment to provide a comprehensive evaluation of the physical condition, performance, and long-term capital needs of the facility. The assessment was performed to support Metro's asset management objectives, including establishing a consistent baseline of asset condition data, identifying operational and maintenance risks, and informing near- and long-term capital planning and investment decisions.

The assessment included qualitative observations of building systems and order-of-magnitude cost opinions associated with identified Corrective Actions. Remaining Useful Life (RUL) estimates were documented for major systems to provide context for lifecycle cost modeling and long-term replacement forecasting. Cost opinions were developed to support evaluation of near-term Corrective Actions necessary to facilitate continued use of the building.

2.2. Corrective Action Categories

To support consistent prioritization, budgeting, and risk management, each identified deficiency or recommended Corrective Action has been assigned to one of the following standardized categories. These categories are intended to clearly communicate the nature of the issue, the urgency of response, and the primary driver for action.

The Corrective Action categories are intended to:

- Provide a consistent framework for interpreting deficiencies across facilities and systems
- Support transparent prioritization of capital and maintenance investments
- Align Corrective Actions with risk, compliance, and asset life-cycle considerations
- Enable meaningful aggregation and analysis at the portfolio level

These categories do not replace professional judgment but serve as a standardized decision-support tool for asset management and capital planning.

Major Maintenance

Major Maintenance includes Corrective Actions required to restore assets that are still within their expected useful life but are exhibiting significant deterioration, performance issues, or deferred maintenance. These actions are typically necessary to maintain acceptable levels of service, reliability, and asset value.

Examples of Major Maintenance include, but are not limited to:

- Significant repairs to building envelope components (e.g., roofing, exterior walls, waterproofing)
- Overhauls or major servicing of mechanical and electrical equipment
- Replacement of major subcomponents that are failing prematurely
- Corrective work addressing chronic operational issues

Major Maintenance actions are generally planned and budgeted as part of ongoing capital renewal or maintenance programs and are prioritized based on asset condition, criticality, and risk of failure.

Life Safety and Code Violation

Life Safety and Code Violation includes deficiencies that pose an immediate or near-term risk to occupant safety, public safety, or regulatory compliance. These Corrective Actions are typically driven by building codes, fire and life-safety standards, occupational safety requirements, or other statutory and regulatory obligations.

Examples include:

- Fire alarm or fire suppression system deficiencies
- Inadequate emergency egress or lighting
- Electrical hazards
- Structural safety concerns
- Non-compliance with accessibility standards

Life Safety and Code Violation items are generally assigned the highest priority and should be addressed as soon as practicable to mitigate risk, ensure compliance, and protect occupants and facility operations.

Additional Evaluation Needed

Additional Evaluation Needed includes conditions where observed deficiencies or uncertainties require further investigation, testing, or specialized assessment before an appropriate Corrective Action can be defined.

This category is used when:

- The extent of deterioration cannot be fully determined through visual inspection alone
- Specialized expertise is required (e.g., structural, geotechnical, environmental, hazardous materials)
- Subsurface or concealed conditions are suspected
- System performance issues cannot be clearly diagnosed

Items in this category typically result in follow-up studies, targeted inspections, or monitoring programs that inform future capital planning and Corrective Actions.

End of Useful Life

End of Useful Life includes assets that have reached or exceeded their expected useful life and for which full replacement is recommended. These assets may still be operational but present increasing risk of failure, inefficiency, or inability to meet current performance requirements.

Examples include:

- HVAC equipment beyond expected service life
- Obsolete electrical or control systems
- Plumbing systems with chronic failure history

- Structural or architectural components no longer viable for repair

End of Useful Life actions are generally treated as capital replacement projects and form a significant portion of long-term recapitalization planning.

2.3. Condition Rating Overview

As part of the assessment, the physical condition of the facility's major building systems and related components are categorized in one of five conditions per category:

Excellent

New or very close to new; component or system is sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.

Good

Satisfactory as-is. A component or system is sound and performing its function, typically within the first third of the component's predicted useful life. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.

Fair

Showing signs of wear and tear but still satisfactory as-is, typically near the middle of its estimated useful life. The component or system is performing adequately at this time but may exhibit signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated RUL.

Poor

Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is required, or repairs are required to restore it to good condition, prevent premature failure, and/or prolong useful life.

Deficient

Component or system has ceased functioning or performing as intended. Replacement, repair, or another significant action is recommended or required.

2.4. Cost Estimating Assumptions

The overall condition and Corrective Action cost data for Metro assets are based upon a parametric approach that is consistent with supporting effective capital and operations-and-maintenance planning and budgeting. Range of accuracy of conceptual level cost estimating for Corrective Actions is typically +/- 30%, and a contingency factors of 20% for design and estimating, and 10% for soft costs are also included in cost estimate mark-ups. See following Table 10 and Table 11.

Conceptual cost projections are based on 2025 market costs for facilities and building systems. Cost projections do not replace typical project-based planning, budgeting, and due diligence. All cost projections represented in this report reflect labor, materials, and markups necessary to repair or replace systems.

Construction Costs and Soft Costs compound when applied to the base cost of labor and materials.

$$\text{Total Cost} = \text{Base Cost} \times (\text{Product of Construction Cost Markups}) \times (\text{Sum of Soft Cost Markups})$$

Construction Cost Item	Markup	Multiplier
Design & Estimating Contingency	20.0%	1.20x
General Conditions, Requirements, and Fee	20.0%	1.20x
Total Construction Cost Markups		1.44x

Table 3. List of Construction Cost Markups

Construction Cost markups are applied on a compounding (multiplicative) basis by converting percentage markups to multipliers and applying them sequentially.

Soft Cost Item	Markup
Design Fees (including CA)	14.5%
Owner Planning & Management Services	10.0%
Project Contingency / Reserve	10.0%
Fixed Furnishings & Equipment	5.0%
Owner Admin or Overhead (e.g., Green design, Policy/Procedures)	4.0%
Owner Consultants (e.g., CM)	4.0%
Utility/Franchise Fees	2.0%
Permits	1.5%
Art	1.0%
Commissioning	0.5%
Testing & Inspection	0.5%
Total Soft Cost Markups	53.0%

Table 4. List of Soft Cost Markups

Soft Cost markups are applied on an additive basis. Items are summed to a total percentage markup which is converted to a multiplier.

All future costs are then normalized to net present value to account for the time value of money and show costs in present dollars. The costs are escalated at a rate of 4.5% per year (the average year-over-year increase in construction costs over the past 15 years) and discounted at a rate of 3.0% per year.

$$\text{Net Present Value} = \text{Total Cost} * \left(\frac{\text{Escalation Rate}}{\text{Discount Rate}} \right)^{\text{Years Until Renewal}}$$

Escalation and Discount Factors	
Escalation	4.5% per year
Discount	3.0% per year

Table 5. List of Escalation and Discount Factors

Facility Condition Index (FCI)

The Facility Condition Index for each facility is an industry standard benchmark for evaluating the condition performance of facilities over time. Agencies develop and change FCIs depending on budget planning and needs. There are various methods for calculating FCI. For this reason, the FCI scores represented in this report should not be compared to those of other organizations unless they use the exact same method of calculation.

The FCI numerator, commonly referred to as Deferred Maintenance, or Backlog in Maintenance and Repair, consists of short-term CAs (i.e., 2025-2030) and mid-term PRs (i.e., 2031-2035).

The FCI calculations used in this report are represented by the total cost of CAs and PRs identified for each building for the period 2025-2035 relative to the estimated 2025 Current Replacement Value (CRV) for each building. This FCI calculation uses CA, PR, and CRV costs in 2025 dollars that do not include escalation.

$$AHH\ FCI = \frac{\text{Corrective Actions (2026 – 2030)} + \text{Predicted Renewals (2031 – 2035)}}{\text{Current Replacement Value (CRV)}}$$

FCI scores are expressed as percentages that range from 0% – 100%. A lower FCI reflects a facility in better condition with lower maintenance needs and associated costs. Conversely, a high FCI score indicates a facility in poorer condition with higher percentage of maintenance needs and associated costs.



FCI is represented by the following categories:

FCI Score	Definition
Good (0%–5%)	The building is in new or well-maintained condition with no visual evidence of wear, soiling, or other deficiencies.
Fair (5%–10%)	The building is subject to wear and soiling but is still in a serviceable and functioning condition.
Poor (10%–60%)	The building has been subjected to hard or long-term wear and is nearing the end of its useful or serviceable life.
Very Poor (60%–100%)	The building has reached the end of its useful or serviceable life. Renewal is now necessary.


Table 6. FCI scoring categories

Current Replacement Value (CRV)


The Current Replacement Value of buildings is based upon a cost model for the use-type of each building and factors the cost model's estimated cost per square foot by the gross square foot area of the building. CRVs should include cost markups to reflect full design and construction costs for the current year's construction market. CRV does not normally include an escalation factor, nor demolition costs of the current building. The primary use of modelling CRVs for buildings is to calculate FCIs for benchmarking purposes.

3. Building Summary

3.1. Facility Overview



Year of original construction	1987
Facility size (gross sq. ft.)	101,074
Number of floors	5
Address	710 SW Main St., Portland, OR 97205
Current Replacement Value	\$212,916,992



3.2. Condition Assessment

Theater Summary

See Appendix A for a detailed theater narrative summary.

Architectural Summary

The AHH is a six-story performing arts facility (Basement, Floors 1-5) constructed in 1987. It contains three theaters serving a broad range of public performances: the Newmark Theatre (880 seats), the Dolores Winningstad Theatre (304 seats), and the Brunish Theatre (200 seats). The building structure consists of concrete frames and slabs supporting both public and back-of-house functions. Portions of the site are subject to a ground lease with the First Unitarian Church; the FCA did not differentiate ownership boundaries unless physically distinct, and no separate church-controlled areas were identified.

The interior architecture largely reflects the original 1987 design and supports the three theaters through a combination of public areas, performance support spaces, and back-of-house functions. Floors 1 through 4 are open to the public, while the basement includes facility and support spaces, and the fifth floor is used primarily for administrative offices.

Public-facing areas incorporate high-end finishes characteristic of a late-1980s performing arts venue, including extensive millwork paneling, broadloom (sheet) carpeting on floors and stairways, painted gypsum board walls and ceilings, and painted interior columns. A signature feature of the building is the central rotunda, extending from the first through fourth floors, surrounded by seating alcoves and capped at Level 5 with a fixed art dome visible from below.

Vertical circulation includes two public elevators integrated into the lobby finishes with millwork cladding, one back-of-house elevator serving support and staff areas with standard commercial finishes, and one freight elevator used for production and material handling.

Stair circulation consists of curved and triangular stair runs connecting public floors, all finished with original broadloom carpeting. Public areas also include decorative guardrails and custom finish details consistent with the building's era and aesthetic.

Back-of-house areas, including offices, support rooms, and operational spaces, feature utilitarian finishes such as carpet tile, resilient flooring, and painted gypsum board walls.

Overall, the interior finishes and millwork remain largely original to 1987. While generally well-maintained, many materials are now approaching or at the end of their useful life due to continuous public use and age.

Structural Summary

The structure is comprised of concrete columns, beams, and mild steel reinforced slabs, with concrete over metal deck and steel framing at roofs and mechanical spaces. Foundations consist of reinforced concrete footings supported by piles.

The building does not meet current seismic code.

Building Envelope Summary

The building envelope of AHH comprises exteriors walls composed of brick & stucco cladding and glass & metal panel curtain walls. Roofing materials include modified bitumen sheet membrane, precast rooftop pavers, wood tile decking, and standing seam metal. Components are in varied condition and a targeted repair campaign to address storm water management systems is recommended.

Mechanical Summary

The HVAC systems at AHH are comprised of a hot and chilled water central plant. Gas-fired boilers provide hot water to the building. These units were upgraded sometime after 2017. The chiller is a multi-stack R410 based chiller installed around 2007 and is approaching end of useful life. An Evapco cooling tower provides evaporative cooling. This unit is approaching end of useful life.

Four-pipe air handling units provide ventilation as well as heating and cooling to the spaces for single zone units or tempered air to terminal boxes with hydronic reheat. Terminal boxes serve spaces such as offices and support areas. Some air handling units have had upgrades to their motors completed along with VFD installation. Others have original motors with a high/low motor system in place. It is recommended to continue with replacement of the motors for the remaining units, including upgrade to VFDs for better speed control.

Domestic hot water is provided via two electric tank style water heaters that were installed in 2020. The units are in good condition.

There is a sprinkler system that serves the building. It is in fair condition with no reported issues. Staff have stated that regular sprinkler head testing is completed per NFPA-25.

The elevator motors were replaced within the past year and are in good condition.

The building control system is Niagara-based. The damper actuators on most air handling units appear to be in good condition, but it appears that other sensors and controls equipment have not been replaced in several years, meaning the equipment is approaching end of useful life. A system upgrade is recommended to the most recent version of Niagara.

Electrical Summary

The building is served by two 3000A, 208Y/120V, three-phase, four-wire electrical services originating from the utility vault located on SW Broadway. Power distribution is divided between two main distribution equipment sections. Section 1 feeds a 1200A subdistribution panel serving the elevators, a motor control center, and two branch panelboards; a 1000A subdistribution panel; and a 1600A subdistribution panel dedicated to dimmer cabinets, along with a total of nine branch panelboards. Section 2 serves a 1600A subdistribution panel that supplies a motor control center, dimmer cabinets, theater lighting, and three branch panelboards, in addition to five branch panelboards overall.

The two main distribution sections are interconnected by a 1000A automatic transfer switch, which supports a 600A emergency motor control center, a 300A emergency motor control center, trickle chargers for Elevators 2 and 3, and three emergency branch panelboards. The standby power system includes a 60 kW diesel generator. Based on observations, the primary distribution equipment, panelboards, and generator appear to date back to the original 1987 construction. Although the equipment is well maintained and currently in good condition, it has exceeded its typical useful life.

The lighting system consists of a variety of fixture types, including recessed downlights, troffers, surface-mounted fixtures with wraparound lenses, strip lights, and open sockets. Overall, the lighting system was found to be in fair condition, with several fluorescent and incandescent fixtures still in use. Low-voltage systems, including telephone, television, intercom, public address, security, and fire alarm, were observed to be in good condition.

3.3. Corrective Action Summary

Säjän identified 52 Corrective Actions based on observations made during the assessment. These actions represent approximately \$12.030M in order-of-magnitude cost opinions.




Figure 3. Recapitalization Need by Year, 2026–2030




Figure 4. Recapitalization Need by Corrective Action Type

3.4. List of Corrective Actions

Additional Evaluation Needed: Column Foundations & Pile Caps



Component

A1112 Column Foundations & Pile Caps

Action Type

Additional Evaluation Needed

Year to Occur

2026

CA ID

AHH-01

Total Cost

\$33,529

Observed Deficiency

In general the structure is in good to excellent condition. However, concrete degradation was noted on exterior columns at the Park and Broadway entrances, and on the columns adjacent to the fireplace in the lobby area. Damage appears to be from water intrusion.

Recommended Action

Degree and extent of degradation should be investigated by a qualified agency or contractor, and repaired as required to restore structural capacity of damaged elements and mitigate corrosion of reinforcement. Likewise source of water intrusion needs to be identified and addressed to ensure it does not continue to occur. Cost reflects price of evaluation only. Further findings from evaluation and recommendations by structural and/or construction contractor may result in additional costs with corrective actions.

Additional Evaluation Needed: Standard Slab on Grade



Component

A1331 Standard Slab on Grade

Action Type

Additional Evaluation Needed

Year to Occur

2026

CA ID

AHH-02

Total Cost

\$26,823

Observed Deficiency

Slabs on grade appear to be in overall good condition. Differential settlement noted between slab on grade and concrete slab over basement area, at the Winnistad entrance adjacent to Main Street.

Recommended Action

Slab should be exposed and investigated by a qualified contractor to determine source of settlement and extents. Options for remediation include demolishing existing slab, preparing subgrade, and recasting it, or leveling it via pressure grouting or similar method.



Additional Evaluation Needed: Moisture Protection



Component

A2222 Moisture Protection

Action Type

Additional Evaluation Needed

Year to Occur

2026

CA ID

AHH-03

Total Cost

\$12,294

Observed Deficiency

Water intrusion observed at Basement Level Storage Room where "DMX Splitters & Accessories" are stored. Reported history of leaks from property management.

Recommended Action

Engage a qualified professional to investigate leak path, generate scope documents, and oversee basement waterproofing.

End of Useful Life: Exterior Wall Construction

**Component**

B2111 Exterior Wall Construction

Action Type

End of Useful Life

Year to Occur

2027

CA ID

AHH-04

Total Cost

\$216,692

Observed Deficiency

Cracks in Newmark south stucco wall (roof level).

Recommended Action

Perform targeted repairs to address deficient materials. Repair roof/gutter system prior to repairs before routing cracks ($>1/16"$) then sealing with elastomeric coating.

End of Useful Life: Exterior Wall Construction



Component

B2111 Exterior Wall Construction

Action Type

End of Useful Life

Year to Occur

2026

CA ID

AHH-05

Total Cost

\$27,941

Observed Deficiency

Cracks in brick. Mortar joints are approaching end of life and capital planning for repointing should be considered.

Recommended Action

Targeted repair to address cracked brick.



End of Useful Life: Parapets



Component

B2112 Parapets

Action Type

End of Useful Life

Year to Occur

2027

CA ID

AHH-06

Total Cost

\$4,536

Observed Deficiency

Organic growth accumulation and failed sealant joints.



Recommended Action

Repair and maintenance campaign to clean surfaces and repair failed sealant joints associated with this component number.

End of Useful Life: Exterior Louvers, Screens and Fencing



Component

B2113 Exterior Louvers, Screens and Fencing

Action Type

End of Useful Life

Year to Occur

2029

CA ID

AHH-07

Total Cost

\$17,216


Observed Deficiency

The louvers sealants along the mechanical equipment room at the roof level are approaching end of useful life at wall transitions.

Recommended Action

Cut out and replace material with polyurethane based sealant and backer rod for 10-20 year useful life. Can be extended to 20-30 years by using premium silicone sealant (price not included in estimate).

Major Maintenance: Exterior Soffits



Component

B2116 Exterior Soffits

Action Type

Major Maintenance

Year to Occur

2030

CA ID

AHH-08

Total Cost

\$61,578

Observed Deficiency

Cracks in stucco soffit and peeled coating at balcony soffits was observed.

Recommended Action

Patch and repair cracked stucco soffits; seal joints/cracks; prep and repaint with exterior-grade coating system.

End of Useful Life: Exterior Windows



Component

B2221 Exterior Windows

Action Type

End of Useful Life

Year to Occur

2026

CA ID

AHH-09

Total Cost

\$50,086

Observed Deficiency

Sealant joints have reached end of useful life and at least one insulated glass unit has been compromised: IGU on south elevation. The observed sealant failure occurred at the ribbon window bands along the east elevation, specifically at the joints where the window frames interface with the adjacent cladding. Given that the surrounding windows are of the same age and similar construction, particularly where dissimilar materials are exposed to thermal cycling, this condition is likely present at other units as well.

Recommended Action

Replace sealant joints associated with this component number and utilized standardized detailing for targeted repairs of windows.

End of Useful Life: Exterior Curtain Walls



Component

B2222 Exterior Curtain Walls

Action Type

End of Useful Life

Year to Occur

2026

CA ID

AHH-10

Total Cost

\$264,747

Observed Deficiency

Active water intrusion and evidence of frequent water intrusion throughout the curtain walls. Configuration at northwest curtain wall prevents proper drainage.



Recommended Action

Replace sealants associated with this component number. Coat area of reentrant corners with PUMA, install drain (if possible), and slope away from structure to address improper drainage. Redo base of wall transitions during PUMA traffic coating application.



End of Useful Life: Exterior Storefronts



Component

B2223 Exterior Storefronts

Action Type

End of Useful Life

Year to Occur

2026

CA ID

AHH-11

Total Cost

\$135,002

Observed Deficiency

Sealants for storefront windows and door jambs have reached end of useful life.



Recommended Action

Remove and replace sealant joints associated with this component number.

Major Maintenance: Exterior Glazed Doors & Entrances



Component

B2331 Exterior Glazed Doors & Entrances

Action Type

Major Maintenance

Year to Occur

2026

CA ID

AHH-12

Total Cost

\$63,929

Observed Deficiency

Sills are allowing water intrusion causing corrosion at jambs.

Recommended Action

Repair/replace door thresholds and sills; install/repair pan flashing as needed; replace weatherstripping and adjust doors to prevent water infiltration.

Major Maintenance: Roof Finishes



Component

B3111 Roof Finishes

Action Type

Major Maintenance

Year to Occur

2026

CA ID

AHH-13

Total Cost

\$129,647

Observed Deficiency

Standing seam metal roofing along Winningstad Stage House rooftop has failed sealant joints and clogged gutters. Ponding was observed at several locations on the paver roof.

Recommended Action

Repair roof finish defects including failed sealant joints and localized membrane/metal repairs; clean and restore drainage.

End of Useful Life: Balcony Walls & Handrails



Component

B3112 Traffic, Toppings & Paving
Membranes

Action Type

End of Useful Life

Year to Occur

2028

CA ID

AHH-14

Total Cost

\$20,708

Observed Deficiency

Traffic coating on deck has reached end of useful life. Drainage system prone to clogging.

Recommended Action

Replace deck coatings with pedestrian traffic coating (e.g. polyurethane methacrylate (PUMA) for 20 year life cycle or Polymethyl methacrylate (PMMA) for 5-10 year life cycle). Plan for regular maintenance (e.g. cleaning surfaces and drainage systems) on a seasonal basis. Monitor drains on a weekly or biweekly basis to ensure clear path for water flow. Utilize manufacturer recommended cleaning products to ensure life of material. Price is based on PMMA coating.

Major Maintenance: Traffic, Toppings & Paving Membranes



Component

B3112 Traffic, Toppings & Paving
Membranes

Action Type

Major Maintenance

Year to Occur

2026

CA ID

AHH-15

Total Cost

\$290,587

Observed Deficiency

Brunish flat roof is in poor condition and
requires replacement.

Recommended Action

We recommend replacing roofing with
continuously supported precast concrete pavers,
to match the character of the mid height roof,
over thermoplastic polyolefin (TPO) membrane.
Close attention to roof transitions and drainage
is required due to history of reported leaks. Price
reflects replacement of membrane and pavers.



Life Safety and Code Violation: Flashings & Trim

**Component**

B3114 Flashings & Trim

Action Type

Life Safety and Code Violation

Year to Occur

2025

CA ID

AHH-16

Total Cost

\$671

Observed Deficiency

Loose diverter flashing at Newmark metal roof.

Recommended Action

Secure loose diverter flashing to prevent it from dislodging completely and falling.

Additional Evaluation Needed: Gutters and Downspouts



Component

B3116 Gutters and Downspouts

Action Type

Additional Evaluation Needed

Year to Occur

2026

CA ID

AHH-17

Total Cost

\$44,706

Observed Deficiency

Evidence of water intrusion was observed in proximity to roof drainage system at most locations. Organic growth accumulation in scuppers.

Recommended Action

Engage a consultant to verify source of leaks, prepare ROM pricing, and oversee contractor selection/performance. Clean all scuppers.



Additional Evaluation Needed: Glazed Roof Openings

**Component**

B3221 Glazed Roof Openings

Action Type

Additional Evaluation Needed

Year to Occur

2026

CA ID

AHH-18

Total Cost

\$33,529

Observed Deficiency

Evidence of active or recent water intrusion observed along an identified leak path during site walk.

**Recommended Action**

Further evaluation is recommended to determine if rotunda assembly sealant is at end of useful life. For now, remove existing sealant and replace with a wet sealant to prevent further water intrusion. Price reflects cost of evaluation only.

Major Maintenance: Roof Hatches



Component

B3222 Roof Hatches

Action Type

Major Maintenance

Year to Occur

2030

CA ID

AHH-19

Total Cost

\$35,052



Observed Deficiency

Evidence of water intrusion observed at roof hatches.

Recommended Action

Replace roof hatch gaskets/seals; repair corrosion and flashing at curb; confirm watertight installation.

End of Useful Life: Interior Door Hardware



Component

C1223 Interior Door Hardware

Action Type

End of Useful Life

Year to Occur

2030

CA ID

AHH-20

Total Cost

\$161,049

Observed Deficiency

Interior door hardware assemblies (levers, locksets, and latches) throughout Hatfield Hall show signs of advanced wear and finish degradation. Several components are no longer supported or manufactured, requiring Metro's Engineering team to salvage functional parts from non-operational doors to keep others in service. Hardware is past its typical useful life and increasingly difficult to maintain.



Recommended Action

Replace interior door hardware assemblies with new, code-compliant commercial-grade hardware compatible with the existing door/frame conditions. Standardize hardware types facility-wide to allow consistent maintenance and future part availability.

End of Useful Life: Fabricated Toilet partitions



Component

C1331 Fabricated Toilet partitions

Action Type

End of Useful Life

Year to Occur

2026

CA ID

AHH-21

Total Cost

\$357,646

Observed Deficiency

Toilet partitions and urinal screens show significant wear including holes, patching, warping, and corrosion, indicating components are at the end of their useful life.

Recommended Action

Replace toilet partitions and urinal screens with new commercial-grade, corrosion-resistant systems.



Life Safety and Code Violation: Stair Handrails and Balustrades



Component

C2114 Stair Handrails and Balustrades

Action Type

Life Safety and Code Violation

Year to Occur

2026

CA ID

AHH-22

Total Cost

\$18,955

Observed Deficiency

At the Park Avenue entrance, the metal handrails along the interior lobby stair are loose and no longer securely fastened. Portions show movement when tested, indicating fastener failure and general deterioration.



Recommended Action

Re-secure the handrails by tightening or replacing anchorage hardware, repair or replace compromised sections, and ensure handrails meet current safety and code requirements.

End of Useful Life: Stair, Tread and Landing Finishes



Component

C2221 Stair, Tread and Landing Finishes

Action Type

End of Useful Life

Year to Occur

2028

CA ID

AHH-23

Total Cost

\$66,265

Observed Deficiency

Sheet carpet on public curved and triangular stair treads and landings is worn and at the end of its useful life, with fading, localized damage and fraying at edges and corners that detracts from appearance and creates potential trip points.

Recommended Action

Replace carpet on all public stair treads and associated landings with new commercial-grade stair carpet, including proper edge binding/nosing and underlayment as required; patch and repair substrate as needed before installation.

End of Useful Life: Wall Finishes to Inside Exterior Walls



Component

C3111 Wall Finishes to Inside Exterior Walls

Action Type

End of Useful Life

Year to Occur

2028

CA ID

AHH-24

Total Cost

\$23,009

Observed Deficiency

Significant water staining, efflorescence, and cracking observed on gypsum wall surfaces and concrete interface at the top of the 5th-floor spiral stair (bulkhead to roof). Moisture intrusion appears to originate at the underside of the metal roof deck and exterior wall junction. Wallboard finish is deteriorated, with visible discoloration, delamination, and cracking.



Recommended Action

Investigate and repair the source of water intrusion at the bulkhead/roof junction. Remove damaged gypsum wall material, perform mold-resistant replacement where required, patch and skim-coat affected wall areas, and repaint to match existing. If water damage extends into the metal deck, coordinate to follow in sequence any roofing/envelope Corrective Actions.

Major Maintenance: Wall Finishes to Interior Walls



Component

C3112 Wall Finishes to Interior Walls

Action Type

Major Maintenance

Year to Occur

2028

CA ID

AHH-25

Total Cost

\$517,695

Observed Deficiency

Millwork wall panels in the public rotunda area show noticeable discoloration, fading, and uneven finish from age, UV exposure, and general wear.

Recommended Action

Replace affected millwork panels to restore uniform appearance and protect wood surfaces.



Major Maintenance: Wall Finishes to Interior Walls



Component

C3112 Wall Finishes to Interior Walls

Action Type

Major Maintenance

Year to Occur

2026

CA ID

AHH-26

Total Cost

\$4,918

Observed Deficiency

Wall finishes adjacent to urinals show moisture-related damage, including bubbling, delamination, and discoloration likely due to repeated splash exposure or failed waterproofing.

Recommended Action

Repair damaged gypsum wallboard, apply appropriate waterproof wall coating or splash protection panel, and seal adjacent penetrations to prevent further moisture damage.



Major Maintenance: Column Finishes



Component

C3113 Column Finishes

Action Type

Major Maintenance

Year to Occur

2026

CA ID

AHH-27

Total Cost

\$46,941

Observed Deficiency

Perimeter lobby column finishes show visible water-related deterioration at the base, including bubbling, cracking, and finish delamination along the column surfaces adjacent to exterior doors and glazing.

Recommended Action

Investigate and repair source of water infiltration, then prep and refinish the affected column surfaces with a durable moisture-resistant coating.

Major Maintenance: Hardeners and Sealers



Component

C3223 Hardeners and Sealers

Action Type

Major Maintenance

Year to Occur

2026

CA ID

AHH-28

Total Cost

\$87,176

Observed Deficiency

Exposed concrete floors show worn, deteriorated sealers with staining, delamination, and surface wear in BOH areas.

Recommended Action

Reapply concrete hardener/sealer to restore surface protection and durability.

Major Maintenance: Flooring



Component

C3224 Flooring

Action Type

Major Maintenance

Year to Occur

2026

CA ID

AHH-29

Total Cost

\$145,294

Observed Deficiency

Stage flooring in the Winningstad and Newmark are in need of new finish flooring panels at minimum. Depending on the exact construction of the stage floors, complete replacement may be required.

Recommended Action

Refinish or replace worn stage flooring panels and finish surfaces; restore resilience/levelness and recoat to manufacturer recommendations.

End of Useful Life: Carpeting



Component

C3225 Carpeting

Action Type

End of Useful Life

Year to Occur

2028

CA ID

AHH-30

Total Cost

\$102,388


Observed Deficiency

Back-of-house carpet is heavily worn and stained throughout multiple rooms and circulation areas. Visible discoloration, embedded stains, and general wear indicate the carpet is nearing the end of its useful life.

Recommended Action

Replace existing back-of-house carpet with new commercial-grade carpet tile or broadloom, including removal and disposal of existing carpet and preparation of substrate as needed.

End of Useful Life: Bases, Curbs and Trim



Component

C3226 Bases, Curbs and Trim

Action Type

End of Useful Life

Year to Occur

2028

CA ID

AHH-31

Total Cost

\$11,044

Observed Deficiency

Surface-mounted wood base along painted drywall corridors in high-traffic public areas is chipped, scuffed, and shows finish deterioration.

Recommended Action

Refinish or replace damaged wood baseboards to restore appearance and provide a durable protective finish.

Additional Evaluation Needed: Ceiling Finishes

**Component**

C3331 Ceiling Finishes

Action Type

Additional Evaluation Needed

Year to Occur

2028

CA ID

AHH-32

Total Cost

\$11,504

Observed Deficiency

Water staining, discoloration, and localized deterioration are visible along the ceiling perimeter adjacent to exterior windows and at curved ceiling sections near ductwork. Conditions suggest historic or ongoing moisture intrusion at multiple locations on the 3rd-5th floors.

Recommended Action

Investigate source of moisture infiltration and repair as needed (coordination required with Envelope/Structural; evaluation cost not included in cost). After resolving moisture source, remove and replace damaged ceiling finish areas and restore adjacent surfaces to match existing texture and paint. Price reflects cost of evaluation only.



End of Useful Life: Chilled Water Systems



Component

D3331 Chilled Water Systems

Action Type

End of Useful Life

Year to Occur

2030

CA ID

AHH-33

Total Cost

\$378,939

Observed Deficiency

The cooling tower and chemical treatment system are approaching end of useful life.

Recommended Action

Replace cooling tower and chemical treatment with new equipment. Price includes estimation of chemical treatment equipment.

End of Useful Life: Chilled Water Systems



Component

D3331 Chilled Water Systems

Action Type

End of Useful Life

Year to Occur

2030

CA ID

AHH-34

Total Cost

\$201,311

Observed Deficiency

The multi-stack chiller is approaching end of normal useful life.

Recommended Action

Replace chiller.

Major Maintenance: Cooling Generating Systems



Component

D3662 Cooling Generating Systems

Action Type

Major Maintenance

Year to Occur

2026

CA ID

AHH-35

Total Cost

\$41,353

Observed Deficiency

B-36 telephone room has insufficient cooling for the space.

Recommended Action

Install a new mini-split AC unit to properly cool space and protect data room equipment. Photo is of example mini-split AC unit installed with elevator upgrade.

Major Maintenance: Heating-Cooling Air Handling Units

**Component**

D3663 Heating-Cooling Air Handling
Units

Action Type

Major Maintenance

Year to Occur

2027

CA ID

AHH-36

Total Cost

\$63,499

Observed Deficiency

ASU-4 is approaching end of useful life.

Recommended Action

Continue with refurbishment of unit by cleaning interior and replacing coils to extend the useful life of the unit. Also investigate addition of a VFD to control the large motor in place of utilizing a large and small motor to control fan speed. Price reflects continued refurbishment costs.

End of Useful Life: Heating-Cooling Air Handling Units



Component
D3663 Heating-Cooling Air Handling Units
Action Type
End of Useful Life
Year to Occur
2030
CA ID
AHH-37
Total Cost
\$85,261
Observed Deficiency
ASU-7 is at end of normal useful life.
Recommended Action
Refurbish unit with new fan motors, VFD, coils, and interior clean.

End of Useful Life: Heating-Cooling Air Handling Units



Component

D3663 Heating-Cooling Air Handling
Units

Action Type

End of Useful Life

Year to Occur

2027

CA ID

AHH-38

Total Cost

\$81,642

Observed Deficiency

ASU-2 is at end of normal useful life.

Recommended Action

Refurbish unit with new fan motors, VFD, coils,
and interior clean.

End of Useful Life: Heating-Cooling Air Handling Units



Component

D3663 Heating-Cooling Air Handling
Units

Action Type

End of Useful Life

Year to Occur

2027

CA ID

AHH-39

Total Cost

\$81,642


Observed Deficiency

ASU-8 is at end of normal useful life.

Recommended Action

Refurbish unit with new fan motors, VFD, coils,
and interior clean.

End of Useful Life: Building Automation Systems



Component

D3668 Building Automation Systems

Action Type

End of Useful Life

Year to Occur

2029

CA ID

AHH-40

Total Cost

\$993,159

Observed Deficiency

Building BAS is approaching EUL. This includes controllers and field sensors.

Recommended Action

Upgrade BAS with new sensors, controllers and user interface to newest version of Niagara. While maintenance practices have extended the life of the unit, it is recommended to budget for replacement in advance of failure.

Additional Evaluation Needed: Air systems Testing & Balancing

**Component**

D3772 Air systems Testing & Balancing

Action Type

Additional Evaluation Needed

Year to Occur

2026

CA ID

AHH-41

Total Cost

\$67,059

Observed Deficiency

Staff report issues with overheating/cooling in spaces throughout the building.

Recommended Action

Conduct retro-commissioning and perform testing, adjusting, and balancing of system to determine baseline operations. Further evaluation on airflow adequacy may be needed depending on results of study.

End of Useful Life: Low Tension Service & Dist.



Component

D5112 Low Tension Service & Dist.

Action Type

End of Useful Life

Year to Occur

2030

CA ID

AHH-42

Total Cost

\$631,644

Observed Deficiency

All equipment is in fair condition but at end of useful life; includes switchboards, distribution panels, motor control centers, and branch panelboards.

Recommended Action

Replace switchboards, distribution panels, motor control centers, and branch panelboards.

End of Useful Life: Lighting Controls



Component

D5223 Lighting Controls

Action Type

End of Useful Life

Year to Occur

2027

CA ID

AHH-43

Total Cost

\$496,657

Observed Deficiency

Lighting Controls in the Brunish, Winningstad, and Newmark are at differing conditions, however all are in need of varying levels of upgrade/replacement to support current production levels. Refer to the supplemental Theatrical Systems Assessment Report in Appendix A for each of the three spaces for specific information on each space.

Recommended Action

Production Lighting Controls need to be modernized to full ANSI standards for sACN & RDM protocols, and dimmers changed out to digital relays when tungsten production lighting fixtures are replaced with LED.

Life Safety and Code Violation: Emergency Light & Power Systems



Component

D5992 Emergency Light & Power Systems

Action Type

Life Safety and Code Violation

Year to Occur

2026

CA ID

AHH-44

Total Cost

\$89,411

Observed Deficiency

Emergency Lighting in the Brunish does not appear to conform to current life safety codes—no means of automatic control bypasses to trigger emergency lighting during a loss of normal power or fire alarm event could be observed.

Recommended Action

Upgrade emergency lighting, egress illumination, and controls to meet current code.

End of Useful Life: Other Special Systems & Devices



Component

D5994 Other Special Systems & Devices

Action Type

End of Useful Life

Year to Occur

2030

CA ID

AHH-45

Total Cost

\$568,408

Observed Deficiency

Orchestra and Seating Lift in the Winningstad has been well maintained, but plans should be made for replacement within the next five years. Original to the facility, the lift is in working condition, but aged. We observed what appeared to be abnormal wear patterns on some of the screw mechanisms, along with what appeared to be metal shavings at the base of some screw jacks. The Orchestra Pit Lift at the Newmark is of similar age and is beginning to show signs of fatigue. Regular maintenance and adjustments may prolong the life of the lifts, but replacement should be planned before failure or loss of functionality occurs. We recommend further review of both the Winningstad and Newmark lifts by a licensed professional.

Recommended Action

Perform a comprehensive inspection and major service of lifts (mechanical, hydraulic, electrical, controls, safety devices); address deficiencies and plan for full replacement when systems reach end of useful life.

End of Useful Life: Theater & Stage Equipment



Component

E1223 Theater & Stage Equipment

Action Type

End of Useful Life

Year to Occur

2027

CA ID

AHH-46

Total Cost

\$4,308,892

Observed Deficiency

Manual and motorized stage rigging in the Winningstad has exceeded the manufacturer's recommended useful life and should be replaced. Manual stage rigging equipment in the Newmark has exceeded the manufacturer's recommended useful life and should be replaced. Pipe grid in the Brunish appears to be well maintained, though no lateral seismic bracing is in place, and should be added as part of any improvements to the space.



Recommended Action

Replace stage rigging components that have exceeded manufacturer recommended service life; inspect supporting structure; perform load testing/certification by qualified rigging contractor.

End of Useful Life: Fixed Casework



Component

E2112 Fixed Casework

Action Type

End of Useful Life

Year to Occur

2028

CA ID

AHH-47

Total Cost

\$27,610

Observed Deficiency

The coat check millwork in the lobby is in poor condition and appears to have reached the end of its useful life. The cubbies and shelves show significant laminate delamination, chipped edges, worn finishes, and exposed substrate. Countertop and sliding cabinet door surfaces are scratched and deteriorated, consistent with original 1987 construction and heavy use. Recommend replacing the full millwork assembly with new commercial-grade casework.

Recommended Action

Replace deteriorated coat check millwork assembly with new durable, commercial-grade casework appropriate for high-traffic public use. Include new shelves, cubbies, cabinet doors, hardware, and resistant finish materials. Restore adjacent finishes as needed during replacement.

End of Useful Life: Fixed Casework



Component

E2112 Fixed Casework

Action Type

End of Useful Life

Year to Occur

2028

CA ID

AHH-48

Total Cost

\$172,565

Observed Deficiency

Stone cocktail tables at alcoves surrounding the rotunda nearing the end of their useful life, there are some with loose anchoring and others with crack surfaces.

Recommended Action

Replace deteriorated stone cocktail tables at alcoves surrounding the rotunda, including correction of anchorage and replacement of cracked surfaces.



End of Useful Life: Furniture & Accessories



Component

E2222 Furniture & Accessories

Action Type

End of Useful Life

Year to Occur

2027

CA ID

AHH-49

Total Cost

\$226,784

Observed Deficiency

Portable Seating in the Brunish is nearing end of life. Portable seating decks and railings appear to be in good condition.

Recommended Action

Replace portable seating systems nearing end of life.

End of Useful Life: Movable Rugs and Mats



Component

E2223 Movable Rugs and Mats

Action Type

End of Useful Life

Year to Occur

2026

CA ID

AHH-50

Total Cost

\$107,294

Observed Deficiency

Portable draperies in the Brunish are at end of useful life and appear unlikely to fail flame testing due to chemical age fading of effectiveness, accumulated aerial content and fabric aging.

Recommended Action

Recommend replacement of existing cotton stage draperies with new drapes, constructed of IFR synthetic velour, thereby eliminating future effects of chemical age failure.

Life Safety and Code Violation: Painted Lines

**Component**

G2115 Painted Lines

Action Type

Life Safety and Code Violation

Year to Occur

2028

CA ID

AHH-51

Total Cost

\$5,062


Observed Deficiency

Curbs on Main St. lack visible indicators to denote a level change.

Recommended Action

Repaint curbs and other level-change features with high-visibility markings to improve pedestrian safety and reduce trip hazards.

End of Useful Life: Site Emergency Power Generation



Component

G4992 Site Emergency Power Generation

Action Type

End of Useful Life

Year to Occur

2030

CA ID

AHH-52

Total Cost

\$378,939

Observed Deficiency

System is at end of useful life.

Recommended Action

Replace generator and accompanying equipment (transfer switches, distribution gear, etc). Price reflects accompanying switchgear and distribution equipment.

3.5. Facility Conditions

Component	Rating
A1111 Wall Foundations	Good
A1112 Column Foundations & Pile Caps	Fair
A1113 Perimeter Drainage & Insulation	Good
A1221 Pile Foundations	Good
A1222 Grade Beams	Good
A1331 Standard Slab on Grade	Fair
A1332 Structural Slab on Grade	Good
A1334 Trenches, Pits and Bases	Good
A2221 Basement Wall Construction	Good
A2222 Moisture Protection	Poor
B1112 Upper Floors Construction	Good
B1113 Balcony Floors Construction	Good
B1114 Ramps	Good
B1115 Exterior Stairs and Fire Escapes	Good
B1117 Other Floor Construction	Good
B1221 Flat Roof Construction	Good
B1222 Pitched Roof Construction	Good
B2111 Exterior Wall Construction	Fair
B2112 Parapets	Fair
B2113 Exterior Louvers, Screens and Fencing	Fair
B2115 Balcony Walls & Handrails	Fair
B2116 Exterior Soffits	Fair
B2221 Exterior Windows	Fair
B2222 Exterior Curtain Walls	Poor
B2223 Exterior Storefronts	Poor
B2331 Exterior Glazed Doors & Entrances	Fair
B2332 Solid Exterior Doors	Fair

Component	Rating
B3111 Roof Finishes	Fair
B3112 Traffic, Toppings & Paving Membranes	Deficient
B3113 Roof Insulation & Fill	Fair
B3114 Flashings & Trim	Fair
B3116 Gutters and Downspouts	Poor
B3221 Glazed Roof Openings	Poor
B3222 Roof Hatches	Fair
C1111 Fixed partitions	Good
C1116 Interior Balustrades and Screens	Fair
C1117 Interior Windows & Storefronts	Good
C1221 Interior Doors	Good
C1222 Interior Door Frames	Good
C1223 Interior Door Hardware	Fair
C1224 Interior Door Wall Opening Elements	Good
C1225 Interior Door Sidelights & Transoms	Good
C1226 Interior Hatches & Access Doors	Good
C1227 Interior Door Painting & Decorations	Good
C1331 Fabricated Toilet partitions	Fair
C1332 Fabricated Compartments & Cubicles	Fair
C1333 Storage Shelving and Lockers	Fair
C1334 Ornamental Metals and Handrails	Good
C1336 Closet Specialties	Fair
C2111 Regular Stairs	Good
C2112 Curved Stairs	Good
C2113 Spiral Stairs	Fair
C2113 Spiral Stairs	Good
C2114 Stair Handrails and Balustrades	Fair

Component	Rating
C2115 Fixed Ladders	Deficient
C2221 Stair, Tread and Landing Finishes	Fair
C2222 Stair Soffit Finishes	Good
C2223 Stair Handrail & Balustrade Finishes	Good
C3111 Wall Finishes to Inside Exterior Walls	Fair
C3112 Wall Finishes to Interior Walls	Good
C3113 Column Finishes	Fair
C3223 Hardeners and Sealers	Fair
C3224 Flooring	Poor
C3224 Flooring	Fair
C3225 Carpeting	Fair
C3226 Bases, Curbs and Trim	Fair
C3331 Ceiling Finishes	Good
C3332 Suspended Ceilings	Good
C3333 Other Ceilings	Good
D1111 Passenger Elevators	Poor
D1112 Freight Elevators	Good
D2111 Water Closets	Good
D2112 Urinals	Good
D2113 Lavatories	Good
D2114 Sinks	Good
D2116 Water Fountains	Good
D2117 Showers	Good
D2118 Drinking Fountains and Coolers	Good
D2120 Water Heaters	Good
D2221 Cold Water Service	Fair
D2222 Hot Water Service	Fair
D2223 Domestic Water Supply Equipment	Fair
D2331 Waste Piping	Fair
D2332 Vent Piping	Fair
D2333 Floor Drains	Good
D2334 Sanitary Waste Equipment	Fair

Component	Rating
D2335 Pipe Insulation	Good
D2441 Pipe & Fittings	Fair
D2444 Pipe Insulation	Good
D2991 Gas Distribution	Fair
D3112 Gas Supply system	Fair
D3115 Hot Water Supply System	Fair
D3221 Boilers	Good
D3222 Boiler Room Piping & Specialties	Fair
D3224 Insulation	Good
D3331 Chilled Water Systems	Fair
D3332 Direct Expansion Systems	Fair
D3441 Air Distribution Systems	Fair
D3442 Exhaust Ventilation Systems	Fair
D3444 Hot Water Distribution	Fair
D3445 Chilled Water Distribution	Fair
D3551 Terminal Self-Contained Units	Fair
D3552 Package Units	Good
D3661 Heating Generating Systems	Fair
D3662 Cooling Generating Systems	Fair
D3663 Heating-Cooling Air Handling Units	Poor
D3664 Exhaust & Ventilating Systems	Fair
D3665 Hoods and Exhaust Systems	Fair
D3666 Terminal Devices	Fair
D3667 General Monitoring & Control	Fair
D3668 Building Automation Systems	Fair
D3771 Piping System Testing & Balancing	Fair
D3772 Air systems Testing & Balancing	Poor

Component	Rating
D3773 HVAC Commissioning	Poor
D4111 Sprinkler Water Supply	Fair
D4114 Wet Sprinkler Systems	Fair
D4221 Standpipe Water Supply	Fair
D4223 Sandpipe Equipment	Fair
D4224 Fire Hose Equipment	Fair
D4331 Fire Extinguishers	Good
D4332 Fire Extinguisher Cabinets	Fair
D4995 Hood & Duct Fire Protection	Fair
D5112 Low Tension Service & Dist.	Fair
D5221 Branch Wiring Devices	Fair
D5222 Lighting Equipment	Poor
D5222 Lighting Equipment	Fair
D5223 Lighting Controls	Poor
D5223 Lighting Controls	Fair
D5331 Public Address & Music Systems	Good
D5332 Intercommunication & Paging System	Good
D5333 Telephone System	Good
D5335 Television Systems	Good
D5336 Clock and Program systems	Good
D5337 Fire Alarm systems	Good
D5338 Security and Detection Systems	Good
D5339 Local Area Networks	Good
D5991 Grounding Systems	Fair
D5992 Emergency Light & Power Systems	Poor
D5992 Emergency Light & Power Systems	Good
D5993 Floor Raceway Systems	Fair
D5994 Other Special Systems & Devices	Poor
E1113 Registration Equipment	Fair
E1116 Laundry & Dry Cleaning Equipment	Fair

Component	Rating
E1118 Office Equipment	Good
E1223 Theater & Stage Equipment	Poor
E1225 Audio-visual Equipment	Fair
E1229 Other Institutional Equipment	Good
E1991 Maintenance Equipment	Fair
E1993 Food Service Equipment	Fair
E1998 Radios	Fair
E2111 Fixed Artwork	Good
E2112 Fixed Casework	Fair
E2113 Blinds and Other Window Treatment	Fair
E2115 Fixed Multiple Seating	Deficient
E2115 Fixed Multiple Seating	Fair
E2222 Furniture & Accessories	Fair
E2222 Furniture & Accessories	Good
E2223 Movable Rugs and Mats	Poor
E2223 Movable Rugs and Mats	Fair
G2111 Bases and Sub-Bases	Good
G2112 Paving & Surfacing	Good
G2113 Curbs, Gutters and Drains	Good
G2114 Guardrails and Barriers	Good
G2115 Painted Lines	Fair
G2331 Paving & Surfacing	Good
G2332 Edging	Fair
G2333 Exterior Steps	Good
G2442 Retaining Walls	Good
G2443 Terrace & perimeter Walls	Good
G2555 Planting	Fair
G2556 Planters	Good
G2557 Irrigation Systems	Good
G2559 Trees	Good
G3114 Fire Protection Distribution & Storage	Fair
G3221 Piping	Fair

Component	Rating
G3443 Hot Water Supply System	Fair
G3551 Chilled Water Piping	Fair
G3554 Cooling Towers on Site	Fair
G3661 Fuel Piping	Fair
G3663 Fuel Storage Tanks	Fair
G4221 Fixtures & Transformers	Fair
G4223 Wiring & Conduits & Ductbanks	Fair

Component	Rating
G4224 Site Lighting Controls	Fair
G4331 Site Communications Systems	Fair
G4332 Site Security & Alarm Systems	Fair
G4992 Site Emergency Power Generation	Fair

Table 7. List of Component Ratings (components not present or not applicable to this facility have been omitted for clarity)

3.6. Asset Inventory and Asset Condition Ratings

The Combined Rating for assets is a derived score representing the current condition of the asset. It is calculated as the average of four factors (asset age, asset condition, asset performance, and level of maintenance), each assessed on a 5-point scale.

Asset ID	Name	Combined Rating	Criticality	Replacement Cost
8309	AHH Air Compressor, main	4-Good	4-Support	\$9,880
8313	AHH ASU 1	3.75-Adequate	2-Essential	\$19,740
12042	AHH ASU 1 VFD: Return Fan	3.5-Adequate	2-Essential	\$7,433
12043	AHH ASU 1 VFD: Supply Fan	3.5-Adequate	2-Essential	\$7,433
8314	AHH ASU 2	3.5-Adequate	2-Essential	\$29,744
12045	AHH ASU 2 VFD RETURN FAN	3.5-Adequate	2-Essential	\$7,433
12044	AHH ASU 2 VFD SUPPLY FAN	3.5-Adequate	2-Essential	\$7,433
8288	AHH ASU 3	3.25-Adequate	2-Essential	\$29,744
8315	AHH ASU 4	2.75-Marginal	2-Essential	\$29,744
8316	AHH ASU 5	2.75-Marginal	2-Essential	\$29,744
8317	AHH ASU 7	3.5-Adequate	2-Essential	\$29,744
8318	AHH ASU 8	3.25-Adequate	2-Essential	\$29,744
8319	AHH ASU 9	2.75-Marginal	2-Essential	\$29,744
8320	AHH Boiler 1	3-Adequate	2-Essential	\$367,000
8321	AHH Boiler 2	3.5-Adequate	2-Essential	\$367,000
8322	AHH Boiler Pump 1	3-Adequate	2-Essential	\$7,210
8323	AHH Boiler Pump 2	3.5-Adequate	2-Essential	\$7,210
8324	AHH CHILLER	3.5-Adequate	2-Essential	\$384,740
8325	AHH CHILLER PUMP 1	3.5-Adequate	2-Essential	\$18,448
8326	AHH CHILLER PUMP 2	3.5-Adequate	2-Essential	\$18,448

Asset ID	Name	Combined Rating	Criticality	Replacement Cost
8333	AHH Condenser Pump 1	3.5-Adequate	2-Essential	\$18,448
8334	AHH Condenser Pump 2	3.5-Adequate	2-Essential	\$18,448
8345	AHH EF 10	3.75-Adequate	2-Essential	\$3,894
8335	AHH Cooling Tower	0.75-Non-operable or unsafe	2-Essential	\$229,140
8346	AHH EF 11	3.75-Adequate	2-Essential	\$3,894
8347	AHH EF 12	3.25-Adequate	2-Essential	\$3,894
8348	AHH EF 13	3-Adequate	2-Essential	\$3,894
8338	AHH EF 2	3.25-Adequate	2-Essential	\$3,894
8340	AHH EF 4	3.25-Adequate	2-Essential	\$3,894
8341	AHH EF 6	3.25-Adequate	2-Essential	\$3,894
8357	AHH MCC 1	3.75-Adequate	2-Essential	\$3,240
8352	AHH GENERATOR	4-Good	2-Essential	\$89,220
8356	AHH Manlift, Winningstad	3.75-Adequate	4-Support	\$122,480
	AHH EMCC 1	3.75-Adequate	2-Essential	\$3,240
	AHH TU-101	4-Good	3-Important	\$5,270
	AHH TU-105	4-Good	3-Important	\$5,270
	AHH TU-107	4-Good	3-Important	\$5,270
	AHH TU-108	4-Good	3-Important	\$5,270
	AHH TU-112	4-Good	3-Important	\$5,270
	AHH TU-114	4-Good	3-Important	\$5,270
	AHH TU-116	4-Good	3-Important	\$5,270
	AHH TU-125	4-Good	3-Important	\$5,270
	AHH TU-126	4-Good	3-Important	\$5,270
8359	AHH Water Heaters Domestic No.1	4-Good	2-Essential	\$3,735
8360	AHH Water Heaters Domestic No.2	4-Good	2-Essential	\$3,735
8361	AHH Water Treatment 03	4-Good	3-Important	\$16,980
8366	AHH Winni Pit Elevator	3.75-Adequate	3-Important	\$35,214
8367	AHH WINNI SOUND - Console and Processing	4-Good	4-Support	\$23,980
	Condensing Unit	0-Non-operable or unsafe	3-Important	\$7,448
	Elevator 1	3.75-Adequate	3-Important	\$558,000

Asset ID	Name	Combined Rating	Criticality	Replacement Cost
	Elevator 2	3.75-Adequate	3-Important	\$520,000
	Elevator 3	3.75-Adequate	3-Important	\$520,000
	Split-System Heat Pump	4-Good	3-Important	\$6,850
	Split-System Heat Pump	4-Good	3-Important	\$6,850
	Split-System Indoor Unit	4-Good	3-Important	\$13,870

Table 8. List of Asset Inventory and Asset Conditions

3.7. Prioritized 5-Year List of Corrective Actions

CA ID	Component	Action	Priority	Cost
AHH-01	A1112 Column Foundations & Pile Caps	Conduct further evaluation	1	\$33,529
AHH-02	A1331 Standard Slab on Grade	Repair system	1	\$26,823
AHH-03	A2222 Moisture Protection	Conduct further evaluation	1	\$12,294
AHH-04	B2111 Exterior Wall Construction	Replace system	2	\$216,692
AHH-05	B2111 Exterior Wall Construction	Replace system	1	\$27,941
AHH-06	B2112 Parapets	Replace system	2	\$4,536
AHH-07	B2113 Exterior Louvers, Screens and Fencing	Replace system	3	\$17,216
AHH-08	B2116 Exterior Soffits	Repair system	3	\$61,578
AHH-09	B2221 Exterior Windows	Replace system	1	\$50,086
AHH-10	B2222 Exterior Curtain Walls	Replace system	1	\$264,747
AHH-11	B2223 Exterior Storefronts	Replace system	1	\$135,002
AHH-12	B2331 Exterior Glazed Doors & Entrances	Repair system	1	\$63,929
AHH-13	B3111 Roof Finishes	Repair system	1	\$129,647
AHH-14	B3112 Traffic, Toppings & Paving Membranes	Replace system	2	\$20,708
AHH-15	B3112 Traffic, Toppings & Paving Membranes	Repair system	1	\$290,587
AHH-16	B3114 Flashings & Trim	Rectify safety/code issue	1	\$671
AHH-17	B3116 Gutters and Downspouts	Conduct further evaluation	1	\$44,706
AHH-18	B3221 Glazed Roof Openings	Conduct further evaluation	1	\$33,529
AHH-19	B3222 Roof Hatches	Repair system	3	\$35,052

CA ID	Component	Action	Priority	Cost
AHH-20	C1223 Interior Door Hardware	Replace system	3	\$161,049
AHH-21	C1331 Fabricated Toilet Partitions	Replace system	1	\$357,646
AHH-22	C2114 Stair Handrails and Balustrades	Rectify safety/code issue	1	\$18,955
AHH-23	C2221 Stair, Tread and Landing Finishes	Replace system	2	\$66,265
AHH-24	C3111 Wall Finishes to Inside Exterior Walls	Replace system	2	\$23,009
AHH-25	C3112 Wall Finishes to Interior Walls	Repair system	2	\$517,695
AHH-26	C3112 Wall Finishes to Interior Walls	Repair system	1	\$4,918
AHH-27	C3113 Column Finishes	Repair system	1	\$46,941
AHH-28	C3223 Hardeners and Sealers	Repair system	1	\$87,176
AHH-29	C3224 Flooring	Repair system	1	\$145,294
AHH-30	C3225 Carpeting	Replace system	2	\$102,388
AHH-31	C3226 Bases, Curbs and Trim	Replace system	2	\$11,044
AHH-32	C3331 Ceiling Finishes	Conduct further evaluation	2	\$11,504
AHH-33	D3331 Chilled Water Systems	Replace system	3	\$378,939
AHH-34	D3331 Chilled Water Systems	Replace system	3	\$201,311
AHH-35	D3662 Cooling Generating Systems	Repair system	1	\$41,353
AHH-36	D3663 Heating-Cooling Air Handling Units	Repair system	2	\$63,499
AHH-37	D3663 Heating-Cooling Air Handling Units	Replace system	3	\$85,261
AHH-38	D3663 Heating-Cooling Air Handling Units	Replace system	2	\$81,642
AHH-39	D3663 Heating-Cooling Air Handling Units	Replace system	2	\$81,642
AHH-40	D3668 Building Automation Systems	Replace system	3	\$993,159
AHH-41	D3772 Air systems Testing & Balancing	Conduct further evaluation	1	\$67,059
AHH-42	D5112 Low Tension Service & Dist.	Replace system	3	\$631,644
AHH-43	D5223 Lighting Controls	Replace system	2	\$496,657

CA ID	Component	Action	Priority	Cost
AHH-44	D5992 Emergency Light & Power Systems	Rectify safety/code issue	1	\$89,411
AHH-45	D5994 Other Special Systems & Devices	Replace system	3	\$568,408
AHH-46	E1223 Theater & Stage Equipment	Replace system	2	\$4,308,892
AHH-47	E2112 Fixed Casework	Replace system	2	\$27,610
AHH-48	E2112 Fixed Casework	Replace system	2	\$172,565
AHH-49	E2222 Furniture & Accessories	Replace system	2	\$226,784
AHH-50	E2223 Movable Rugs and Mats	Replace system	1	\$107,294
AHH-51	G2115 Painted Lines	Rectify safety/code issue	1	\$5,062
AHH-52	G4992 Site Emergency Power Generation	Replace system	3	\$378,939
Total				\$12,030,288

Table 9. Prioritized 5-Year List of Corrective Actions

3.8. Prioritized 6–10 Year List of Predicted Renewals

Component	Action	Priority	Cost
E1116 Laundry & Dry Cleaning Equipment	Replace system	1	\$106,861
E1993 Food Service Equipment	Replace system	1	\$230,723
B3113 Roof Insulation & Fill	Replace system	2	\$2,574,916
D2221 Cold Water Service	Replace system	2	\$989,968
D2222 Hot Water Service	Replace system	2	\$1,024,967
D2223 Domestic Water Supply Equipment	Replace system	2	\$1,244,960
D2331 Waste Piping	Replace system	2	\$762,475
D2332 Vent Piping	Replace system	2	\$659,979
D3442 Exhaust Ventilation Systems	Replace system	2	\$1,587,448
D5991 Grounding Systems	Replace system	2	\$324,989
B1221 Flat Roof Construction	Replace system	3	\$15,027,851
B2331 Exterior Glazed Doors & Entrances	Replace system	3	\$977,840
B3111 Roof Finishes	Replace system	3	\$6,916,929
B3114 Flashings & Trim	Replace system	3	\$970,120
C1116 Interior Balustrades and Screens	Replace system	3	\$970,120
C1117 Interior Windows & Storefronts	Replace system	3	\$1,518,225
C1333 Storage Shelving and Lockers	Replace system	3	\$18,013
C1334 Ornamental Metals and Handrails	Replace system	3	\$684,488

Component	Action	Priority	Cost
D2112 Urinals	Replace system	3	\$241,887
D2113 Lavatories	Replace system	3	\$308,791
D2114 Sinks	Replace system	3	\$334,524
D2117 Showers	Replace system	3	\$51,465
D2334 Sanitary Waste Equipment	Replace system	3	\$82,344
D2441 Pipe & Fittings	Replace system	3	\$342,244
D2991 Gas Distribution	Replace system	3	\$123,517
D3112 Gas Supply system	Replace system	3	\$591,850
D3222 Boiler Room Piping & Specialties	Replace system	3	\$2,421,440
D3441 Air Distribution Systems	Replace system	3	\$5,362,678
D3444 Hot Water Distribution	Replace system	3	\$2,526,943
D3445 Chilled Water Distribution	Replace system	3	\$2,542,383
D3664 Exhaust & Ventilating Systems	Replace system	3	\$862,043
D3666 Terminal Devices	Replace system	3	\$514,652
D4221 Standpipe Water Supply	Replace system	3	\$226,447
D4223 Standpipe Equipment	Replace system	3	\$102,930
D4224 Fire Hose Equipment	Replace system	3	\$140,026
D5223 Lighting Controls	Replace system	3	\$1,628,875
D5331 Public Address & Music Systems	Replace system	3	\$3,311,788
D5332 Intercommunication & Paging System	Replace system	3	\$936,667
D5333 Telephone System	Replace system	3	\$2,084,342
D5335 Television Systems	Replace system	3	\$1,080,770
D5336 Clock and Program systems	Replace system	3	\$707,647
D5337 Fire Alarm systems	Replace system	3	\$1,827,016
D5338 Security and Detection Systems	Replace system	3	\$2,655,607
D5339 Local Area Networks	Replace system	3	\$2,081,769
E2113 Blinds and Other Window Treatment	Replace system	3	\$1,343,243
Total			\$71,024,761

Table 10. Prioritized 6–10 Year List of Predicted Renewals

3.9. Estimated 10–20 Year Maintenance and Recapitalization Need

Component	Cost
B2332 Solid Exterior Doors	\$298,747

Component	Cost
C1111 Fixed partitions	\$8,893,247
D2111 Water Closets	\$464,717
D2116 Water Fountains	\$476,200
D2118 Drinking Fountains and Coolers	\$152,140
D2120 Water Heaters	\$677,969
D2333 Floor Drains	\$193,632
D2335 Pipe Insulation	\$341,958
D2444 Pipe Insulation	\$196,254
D3115 Hot Water Supply System	\$1,002,085
D3221 Boilers	\$1,647,345
D3224 Insulation	\$561,533
D3332 Direct Expansion Systems	\$3,894,772
D3551 Terminal Self-Contained Units	\$824,320
D3552 Package Units	\$359,603
D3661 Heating Generating Systems	\$1,303,189
D4111 Sprinkler Water Supply	\$414,926
D4114 Wet Sprinkler Systems	\$1,064,977
D4331 Fire Extinguishers	\$11,065
D4332 Fire Extinguisher Cabinets	\$22,129
D5221 Branch Wiring Devices	\$3,601,557
D5992 Emergency Light & Power Systems	\$1,673,535
Total	\$28,075,897

Table 11. Estimated 10–20 Year Maintenance and Recapitalization Need

3.10. Estimated 20–30 Year Maintenance and Recapitalization Need

Due to the age of this facility, no expected replacements are due to occur in this time horizon.

Component	Cost
None	\$0
Total	\$0

Table 12. Estimated 20–30 Year Maintenance and Recapitalization Need

3.11. Recommendations for Follow-up Assessments

The FCA identified several deficiencies which require additional evaluation and analysis to understand the extent and cause of the issue. Those deficiencies and estimations of their costs are summarized below. These costs are included in the prioritized 5-year list of corrective actions.

CA ID	Component	Deficiencies	Cost
AHH-01	A1112 Column Foundations & Pile Caps	In general the structure is in good to excellent condition. However, concrete degradation was noted on exterior columns at the Park and Broadway entrances, and on the columns adjacent to the fireplace in the lobby area. Damage appears to be from water intrusion.	\$33,529
AHH-02	A1331 Standard Slab on Grade	Slabs on grade appear to be in overall good condition. Differential settlement noted between slab on grade and concrete slab over basement area, at the Winnistad entrance adjacent to Main Street.	\$26,823
AHH-03	A2222 Moisture Protection	Water intrusion observed at rug room. Reported history of leaks from property management.	\$12,294
AHH-17	B3116 Gutters and Downspouts	Evidence of water intrusion was observed in proximity to roof drainage system at most locations. Organic growth accumulation in scuppers.	\$44,706
AHH-18	B3221 Glazed Roof Openings	Evidence of active or recent water intrusion observed along an identified leak path during site walk.	\$33,529
AHH-32	C3331 Ceiling Finishes	Water staining, discoloration, and localized deterioration are visible along the ceiling perimeter adjacent to exterior windows and at curved ceiling sections near ductwork. Conditions suggest historic or ongoing moisture intrusion at multiple locations on the 3rd -5th floors.	\$11,504


CA ID	Component	Deficiencies	Cost
AHH-41	D3772 Air systems Testing & Balancing	Staff report issues with overheating/cooling in spaces throughout the building.	\$67,059
Total			\$229,445

Table 13. Recommended Follow-up Assessments and Estimated Costs

4. How to use this Report

The information in this report provides Metro with objective recommendations and cost estimates that should be considered for both short and long-term planning and budgeting. To effectively utilize the data, the following recommendations include:

1. Review Corrective Action improvement scope and costs. This will identify trends in what systems require the most work and provide high-level capital planning figures.
2. Review Corrective Actions per facility to understand the recommended work items by scope and cost.
3. Consider opportunities for combining recommended improvements based on similar scope, schedule, and budget concerns. Combining scope of work options will provide efficiencies of scale and work trades.
4. Assess the building value and functionality and compare against the cost to maintain the facility.
5. Assign a dedicated project manager (i.e., Department staff or consultant) for selected improvements and begin further planning and refinement of scope of work for each improvement. Each proposed project should have an experienced facilities professional to develop a scope of work.
6. Understand that this FCA is a starting point for the Department's formal asset management strategy.
 - a. The cost projections provided in this report are useful to illustrate Rough Order of Magnitude (ROM), budgetary costs that are -30% / +50% and are intrinsically conservative. Do not rely on these costs for cost management of projects; rather, from this initial baseline, project managers will be better informed about the future development of more detailed third-party cost estimates.
 - b. The description of work to be performed to address Corrective Actions must be reviewed and more fully detailed by a qualified facility professional, architect, engineer, or construction manager to minimize construction risk. Where applicable, a detailed design be completed.



5. Appendices

Narrative Summary

Project: Portland’5 Facility Condition Assessment
Subject: Brunish, Winningstad, Newmark, Arlene Schnitzer Concert Hall, Keller Auditorium
Date: 3/11/2026
From: Chris Ochocki, ASTC

Introduction

Project History and Narrative Summary Purpose

Over the course of multiple visits in November and December of 2026, PLA Designs represented by Chris Ochocki, ASTC, Jessica Irish, Nate Zwainlesk, & Thomas Cowdery toured the Brunish, Winningstad, & Newmark Theaters, the Arlene Schnitzer Concert Hall, and the Keller Auditorium. The intent of our visits to each of the Portland’5 performance venues was to observe, report, and provide recommendations for the theatrical systems and equipment in the spaces.

Our observations and reporting of recommended corrective actions have been recorded as part of the overall facility condition assessment project led by Sazan Group. However, due to the specialized nature of the technical systems and equipment for performing arts venues, many of the items observed, and our recommendations for said items, require context than exceeds space limitations in the executive summaries. This narrative summary report of our findings and recommendations is intended to provide the extra context required and should serve as a higher definition document for future corrective actions for the theatrical systems and equipment included herein.

Recognition of Excellent Facility Stewardship by P5 Staff

As we toured each space, a common theme emerged. For every technical system, at every venue without fail, every piece of equipment observed was in the best condition possible. This was true for the systems and equipment we observed which were brand new, the systems and equipment we observed which were long ago obsolete and in desperate need of replacement, and the systems and equipment in all stages of life in-between. Our reporting would be incomplete without first acknowledging the Portland’5 Operations Staff, as well as the many stagehands and department heads whose passion and excellent stewardship of the systems and equipment in their charge can be observed throughout each space we observed.

Systems & Equipment Groupings

Our observations, reporting, and recommended corrective actions for the systems and equipment included in our scope of work are grouped into the following categories:

- Stage Flooring Systems
- Manual & Motorized Stage Rigging Systems
- Stage, Decorative, & Variable Acoustic Draperies

- Fixed Pipe Grid Systems
- Motorized Orchestra Pit, Stage, and Seating Lifts
- Theatrical Lighting Control Systems
- General Illumination Fixtures
- Production Lighting Fixtures
- Production Audio/Visual Systems
- Fixed Audience Seating
- Portable Audience Seating & Seat Decking
- Technical Access and Other Life Safety Items
- Historic Interior Finishes

Note that some system groups listed above may not be present in each of the venues observed. Additionally, detailed commentary on audiovisual systems is somewhat lacking, due to variables which are often subjective rather than objectively obvious. Our comments are therefore generalized.

As with most complex technical systems, theatrical systems and equipment are often interconnected in ways that may not seem readily apparent. In many cases systems which seem fully independent of each other are in fact intertwined. With very few exceptions, it is not possible to replace or repair an item without impacting many other items in space. For clarity of reporting, we have isolated the theatrical systems for each space observed into separate groups. However, we have also done our best to highlight instances where our recommendations for repair or replacement of a specific component will likely have an impact on other items in the space, up to and including requiring modifications to and/or replacement of equipment in good or working condition.

Brunish Theater – Observations & Recommendations

Masking Draperies (Brunish Theater)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	None	No

Observations

- Most of the drapery system includes sewn-in manufacturer labels identifying them as IFR (inherently flame-resistant) velour drapery products of Stagecraft Industries, Inc., installed in March 2012. Other drapes within the system were unlabeled, but their observed condition, material wear, and degradation patterns strongly suggest they are of similar age or older. The overall drapery system shows extensive signs of deterioration, including moisture-related staining, weakened backing, structural tearing, fraying, hem failures, and previous repairs. The damage is systemic rather than isolated, indicating end-of-life conditions.
- Extensive tide-line staining indicates repeated moisture exposure.
- Binder migration and backing hardening visible across multiple panels.
- Multiple structural tears, including one long repaired tear at a weakened elevation.

- Hem separation and drag damage where drapes contact the floor.
- Fraying and emerging tears suggest compromised tensile strength.
- Multiple panels exhibit symptoms consistent with binder migration, including hardened lower sections, tide-line staining, and backing distortion. Combined with the observed structural failures (horizontal tears and frayed openings occurring precisely within the affected elevation), these conditions strongly suggest that the binder system has been compromised, contributing to the overall degradation and reduced remaining service life of the drapery system.
- Damage is consistent with long-term storage and age-related degradation.

Recommendations

- The widespread physical degradation, persistent moisture damage, and structural failure of multiple panels, indicate that replacement of the drapery system should be considered a near-term priority. Continued use increases the likelihood of additional tears and shortens aesthetic life onstage.

Pipe Grid System (Brunish Theater)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	10+ Years	No

Observations

- The Pipe Grid System appears to be constructed from 1.5" Schedule 40 steel pipe, painted to match the ceiling above. The pipe grid supports both portable theatrical equipment clamped to the pipe grid members, as well as permanent and semi-permanent equipment mounted to, or immediately adjacent to the pipe grid members. The pipe grid components appear, based on a visual review, to be in good overall condition. However, given the age of the pipe grid and limited available as-built documentation, a detailed structural review, beyond the scope of this report is recommended.
- The existing Pipe Grid system appears to be in good condition.
- Cross-connect clamps between pipe grid members appear secure.
- Ledger brackets supporting pipe grid members terminating at perimeter walls appear to be well attached to walls, and connections to pipe grid members appear secure.
- Threaded rod hangers appear to be in good condition.
- Portable equipment attached to the pipe grid appears to be properly secured, including the appropriate safety cables per best theatrical practice.
- No lateral seismic bracing serving the pipe grid system was observed.
- We were unable to observe any documentable point load, or overall system load ratings for the pipe grid system.

Recommendations

- A detailed hands-on structural review and analysis of the pipe grid components and pipe grid connections to structure should be performed by a registered structural engineer, so that accurate load ratings for the pipe grid system are known.
- Though not required at the time of installation, the addition of new seismic bracing of the pipe grid system should be considered as part of work scope for systems and equipment permanently or semi-permanently attached to the pipe grid system.

Theatrical Lighting Controls (Brunish Theater)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Poor	1-5 Years, depending on use	Yes (Emergency egress controls)

Observations

- Production Lighting Power Controls consists of an array of portable dimmer bars which have been configured for semi-permanent attachment to the Pipe Grid System. The dimmer bars appear to be in fair condition but are now obsolete. Sourcing replacement parts for the dimmer bars is likely to become problematic as the manufacturer has ceased operations.
- General Lighting Controls are partially integrated with production lighting controls. Manufacturer support for the general lighting controls system is anticipated to end in the next 5 years.
- **No means of automatic control bypasses to trigger emergency lighting during a loss of normal power or fire alarm event could be observed.**
- There are currently no hard-wired or dedicated means to control modern LED production lighting instruments present in space.
- The DMX Data Input receptacle for controlling the dimmer bars is located on the opposite side of the space from the existing control location, necessitating a long run of portable patch cable(s) between the stage lighting console and the control receptacle.
- DMX data distribution (required for the control of modern stage lighting fixtures) is limited.
- Existing panel boards serving obsolete dimmer bars are in good condition and have ample capacity to support reconfiguration of the system from obsolete incandescent fixtures to modern LED units.
- Existing stations for general lighting controls are obsolete, with manufacturer support for the devices likely to be ending within the next 5 years.
- Existing company switch is in excellent condition and should remain to allow for future growth.

Recommendations

- Remove obsolete dimmer bars and existing panelboards and replace them with mains fed relay panels with integral circuit breakers, utilizing existing feeders.

- Provide new multi-outlet power receptacles fed from new relay panels at the locations of the removed dimmer bars.
- Provide new hardwired lighting network and DMX/RDM data distribution adjacent to new power receptacles and at elevated control location.
- Replace existing Architectural controls to allow for new LED General Illumination fixtures described below and connect to building's Fire Alarm Control Panel per current life safety codes and best theatrical practice.

General Lighting Fixtures (Brunish Theater)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	1 Year	No

Observations

- Existing general illumination consists of two separate groups of fixtures. A grid linear work light fixtures, lamped with fluorescent tubes of varying color temperatures, suspended just above the pipe grid, and incandescent production lighting fixtures, clamped to the pipe grid and plug connected to existing dimmer bars.
- Lamps of differing color temperature, not color balanced to production lighting fixtures likely produce shifts in perceived color between set construction/design and performances.
- Production lighting fixtures serving as house lighting are obsolete, procurement of replacement lamps with theatrical quality dimming is likely to become problematic within the next five to ten years.

Recommendations

- Remove existing fluorescent fixtures and obsolete production lighting fixtures serving as house lighting fixtures with new LED cylinder downlights with smooth dimming to less than .01% and high color rendering. Integrate with new house lighting, emergency egress, and production lighting controls systems.

Production Lighting Fixtures (Brunish Theater)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	None	No

Observations

- Existing production lighting fixture inventory consists of obsolete incandescent units in poor condition and in need of replacement.

Recommendation

- Replace existing incandescent fixtures with a basic complement of new LED units.

Production Audio/Video Systems (Brunish Theater)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-5 Years	No

Observations

- A/V systems in the space are limited, though appropriate for the size typical use of the space. However, many existing components are obsolete or nearing obsolescence.

Recommendations

- Replace aging components with new.

Portable Audience Seating & Seat Decking (Brunish Theater)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor (Portable Seating)	1 Year	No

Observations

- Portable seating units have exceeded their expected useful life and need to be replaced.
- Upholstery on existing seating units is well worn on many seating units. Some units are beginning to show signs of extreme wear.
- Self-rising mechanisms on many seats appear to be failing. Self-rising functionality is critical to allow life safety code conformance with existing row to row spacing as configured.
- Railings for portable decking system appear to be well secured to existing seating decks.
- Portable decking units are aging but appear very well maintained. Seating decks appear to be in good condition, with a solid and premium feel.
- Barring abuse or accidental damage, the existing seat decking system should remain functional for the next 8-12 years.

Recommendations

- Replace existing portable seating units in the Brunish with new units. We recommend the new units be provided in the same type and configuration as the portable audience seating in the Winningstad Theater to allow for consolidated maintenance and to provide a uniform experience across P5 venues with portable audience seating.

Technical Access and Other Life Safety Items (Brunish Theater)

Observations

- Gaps in railings at elevated control platform exceed the allowable dimensions described in current OSHA requirements.
- Color temperature of general lighting fixtures in Brunish Dressing Rooms appears to be in the 4000K range. Best practices for these areas are 3000K CCT & 90+ CRI lighting.

Recommendations

- Reconfigure railing installation to remove gaps larger than those that allow for a 4" sphere to pass through.
- Replace dressing room fixtures with new fixtures, color matched to new LED production lighting fixture's base color temperature. (Typically 3000K.)

End of Brunish Observations & Recommendations

Winningstad Theater – Observations & Recommendations

Stage Flooring Systems (Winningstad)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-5 Years	No

Observations

- Existing finish floor panels appear to have been replaced with new tempered hardboard. Due to pandemic related supply chain shortages, available stock of tempered hardboard has been prone to pre-mature failure when used in stage floor applications.

Recommendations

- Carefully observation of finish floor panels to mitigate the potential of pre-mature failure. Anticipate replacement of entire stage floor in advance of typical life cycle for performance space flooring.

Manual & Motorized Stage Rigging Systems (Winningstad)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	1 Year	No

Observations

- Existing manual counterweight rigging sets have exceeded the manufacturer's published recommended useful life.
- We observed multiple locations where lifting lines for FOH lighting hoists are rubbing against adjacent lifting lines, or other equipment adjacent to lifting lines.
- Motorized line sets appear to be in working order, but many components have exceeded the manufacturer's published recommended useful life.

Recommendations

- Replace existing manual and motorized line sets with new, matching quantities and configuration of existing line sets.

Stage, Decorative, & Variable Acoustic Draperies (Winningstad)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	7-9 Years	No

Observations

- The majority of the drapery system includes sewn-in manufacturer labels identifying them as Rose Brand, Velour 54 in IFR (inherently flame-resistant) 25 oz. Charisma drapery products installed in May 2013.
- The Winningstad's drapery system is aged but very well maintained. The draperies observed are consistent with expected wear patterns for IFR velour in long-term theatre use. Replacement is not immediately required, but capital planning for renewal within the next 7–9 years is appropriate based on age, aesthetic wear, and lifecycle expectations.

Recommendations

- No conditions were observed that indicate an immediate need for total system replacement; however, based on age, material type, and observed wear patterns, planning for replacement within the next 7–9 years is recommended.

Motorized Orchestra Pit, Stage, and Seating Lifts (Winningstad)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-5 Years	No

Observations

- Lift system has been well maintained but is beginning to show signs of age.
- Abnormal wear patterns, and metal shavings were observed at multiple screw jack locations.
- High pitched whine during system, during lift operation was observed.

- Users indicate lift system is inspected/maintained annually.

Recommendations

- Continue regular maintenance/inspection by specialized elevator/lift contractor.
- Even with regular maintenance and care, mechanical systems are subject to normal wear which can lead to failure. Planning for replacement of lift system within 5 years is recommended.

Theatrical Lighting Controls (Winningstad)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-5 Years	No

Observations

- General Lighting controls were replaced in 2017 and conform to all current life safety codes.
- Production lighting controls and distribution systems are configured primarily for incandescent stage lighting instruments.
- Existing controls can accommodate a limited number of LED based production lighting fixtures.
- Existing Stage Lighting Distribution equipment is in fair condition, and configured primarily for incandescent production lighting fixtures.
- Limited DMX/RDM and lighting network data distribution is present, but is inadequate to support a full complement of LED production lighting fixtures.

Recommendations

- Replace existing production lighting distribution equipment with new, configured to fully support an inventory of all LED production lighting fixtures.
- Replace existing dedicated dimmer modules located in existing stage lighting dimmer racks with new dedicated relay modules.

General Illumination Fixtures (Winningstad)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Excellent	10-15 Years	No

Observations

- General and Work Lighting Fixtures are LED, replaced in 2017 and in excellent condition.

Recommendations

- None at this time.

Production Lighting Fixtures (Winningstad)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Poor	1-3 Years	No

Observations

- Existing production lighting complement consists of mostly incandescent fixtures nearing or exceeding obsolescence.
- Fixtures are well maintained and in working condition, but sourcing of production quality lamps is likely to become problematic in the near future.

Recommendations

- Replace existing incandescent fixture inventory with new LED units.

Production Audio/Visual Systems (Winningstad)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	5-10 Years	No

Observations

- Existing equipment appears to be current generation and in good working condition.

Recommendations

- None at this time.

Fixed & Portable Audience Seating (Winningstad)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	10-15 Years	No

Observations

- Existing fixed and portable seating units are in good condition and show minimal signs of wear.

Recommendations

- None at this time.

End of Winningstad Observations & Recommendations

Newmark Theater – Observations & Recommendations

Stage Flooring Systems (Newmark)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-5 Years	No

Observations

- Existing finish floor panels appear to have been replaced with new tempered hardboard. Due to pandemic related supply chain shortages, available stock of tempered hardboard has been prone to pre-mature failure when used in stage floor applications.

Recommendations

- Carefully observation of finish floor panels to mitigate the potential of pre-mature failure. Anticipate replacement of entire stage floor in advance of typical life cycle for performance space flooring.

Manual & Motorized Stage Rigging Systems (Newmark)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Poor	1 Year	No

Observations

- Existing manual counterweight rigging sets have exceeded the manufacturer's published recommended useful life.

Recommendations

- Replace existing manual line sets with new, matching quantities and configuration of existing line sets.

Stage, Decorative, & Variable Acoustic Draperies (Newmark)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	7-9 Years	No

Observations

- The majority of the drapery system includes sewn-in manufacturer labels identifying the drapery. The 2014 iWeiss masking drapery, fabricated from Rose Brand 25 oz IFR Charisma velour, remains in sound operational condition despite its age. The drapes exhibit normal long-term wear characteristics, including surface fading, nap compression, and minor soiling, but no failures that compromise their structural or functional integrity. Stitching, panel alignment, and

fabric performance remain stable. Given the durability of IFR Charisma velour and the well-executed original construction, these drapes are expected to remain serviceable for a minimum of 7 additional years with routine handling and maintenance.

- By contrast, the 2017 Rose Brand border drapery, although made from the same 25 oz IFR Charisma velour, demonstrates significant construction-related deficiencies. The fabric itself is not the limiting factor; rather, the borders show poorly executed original stitching, including extremely narrow seam allowances, evidence of multiple removed and re-sewn seam lines, and areas of active seam stress and separation. These deficiencies reflect variable fabrication quality rather than material degradation. As a result, despite being newer and made from the same base velour product, these borders have a substantially shortened remaining lifespan and are likely to require replacement within the next five years, potentially sooner depending on use frequency.

Recommendations

- The Newmark Theatre's drapery system remains broadly operational, with the 2014 iWeiss masking drapery showing age-appropriate fading, nap wear, and minor soiling while still retaining full structural and functional integrity. Remaining serviceable for longer than 5 years. In contrast, the 2017 Rose Brand border drapery, though made from the same IFR Charisma fabric, displays significant fabrication-related deficiencies. These issues stem from original construction quality rather than material degradation, resulting in a substantially shorter remaining useful life and the need for replacement within the next five years, potentially sooner depending on progression of seam failure.
- However, it should be noted that the grand drape, as part of the iWeiss 2014 drapes was fabricated from Peacock Charisma velour, is also generally serviceable despite localized fading and minor wear around pull-handle attachment points. Importantly, this fabric was obviously selected to match the color palette of the auditorium seating upholstery. If the venue intends to reupholster or replace the seating in the coming years, it is recommended that the grand drape be replaced concurrently. Staggered replacement, where new seating fabric is installed alongside an older, naturally faded drape, will result in highly noticeable color mismatch, making either the drape or the seating appear prematurely worn. Coordinated replacement will preserve visual cohesion and avoid a scenario where one element's fresher dye lot makes the other appear detrimentally faded.

Motorized Orchestra Pit Lift (Newmark)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-5 Years	No

Observations

- Lift system has been well maintained but is beginning to show signs of age.
- Users indicate lift system is inspected/maintained annually.

Recommendations

- Continue regular maintenance/inspection by specialized elevator/lift contractor.
- Even with regular maintenance and care, mechanical systems are subject to normal wear which can lead to failure. Planning for replacement of lift system within 5 years is recommended.

Theatrical Lighting Controls (Newmark)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-5 Years	No

Observations

- General Lighting controls were replaced in 2017 and conform to all current life safety codes.
- Production lighting controls and distribution systems are configured primarily for incandescent stage lighting instruments.
- Existing controls can accommodate a limited number of LED based production lighting fixtures.
- Existing Stage Lighting Distribution equipment is in fair condition, and configured primarily for incandescent production lighting fixtures.
- Limited DMX/RDM and lighting network data distribution is present, but is inadequate to support a full complement of LED production lighting fixtures.

Recommendations

- Replace existing production lighting distribution equipment with new, configured to fully support an inventory of all LED production lighting fixtures.
- Replace existing dedicated dimmer modules located in existing stage lighting dimmer racks with new dedicated relay modules.

General Illumination Fixtures (Newmark)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Excellent	10-15 Years	No

Observations

- General and Work Lighting Fixtures are LED, replaced in 2017 and in excellent condition.

Recommendations

- None at this time.

Production Lighting Fixtures (Newmark)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Poor	1-3 Years	No

Observations

- Existing production lighting complement consists of mostly incandescent fixtures nearing or exceeding obsolescence.
- Fixtures are well maintained and in working condition, but sourcing of production quality lamps is likely to become problematic in the near future.

Recommendations

- Replace existing incandescent fixture inventory with new LED units.

Production Audio/Visual Systems (Newmark)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	5-10 Years	No

Observations

- Existing equipment appears to be current generation and in good working condition.

Recommendations

- None at this time.

Fixed Audience Seating (Newmark)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	1 Year	No

Observations

- Existing fixed seating units have well exceeded their anticipated useful life, and are in need of replacement.

Recommendations

- Replace seating units with new of like kind and layout.

Technical Access and Other Life Safety Items (Newmark)

Observations

- Vertical ladder from mid gallery to loading gallery/grid iron access is open, with no observable safety measures conforming to current OSHA requirements.

Recommendations

- Provide fall arrest and recovery system at vertical ladder between mid and loading galleries.

End of Newmark Observations & Recommendations

Arlene Schnitzer Concert Hall – Observations & Recommendations

Stage Flooring Systems (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	5-10 Years	No

Observations

- Existing stage floor is in good condition and with regular maintenance and care should have an anticipated life of 5-10 years.

Recommendations

- None at this time

Manual & Motorized Stage Rigging Systems (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Poor	1 Year	No

Observations

- Existing manual counterweight rigging sets have exceeded the manufacturer's published recommended useful life.
- Users indicate replacement of manual stage rigging components is scheduled.

Recommendations

- Replace existing stage rigging equipment as currently scheduled.

Decorative, & Variable Acoustic Draperies (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	5 Years	No

Observations

- Decorative draperies are in good condition and if cleaned at regular intervals should have an expected life of not less than 10 years.
- Acoustic draperies at perimeter of house are in generally fair condition and should be able to sustain one more cleaning cycle.

Recommendations

- Clean acoustic draperies within 2 years. Prepare for replacement no later than 5 years after next cleaning cycle.

Motorized Orchestra Pit, Stage, and Seating Lifts (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	5-10 Years	No

Observations

- Lift system has been well maintained and is operated regularly.
- Users indicate lift system is inspected/maintained annually.

Recommendations

- None at this time

Theatrical Lighting Controls (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Excellent	10-15 Years	No

Observations

- New lighting controls equipment was staged for installation at time of observation.

Recommendations

- None at this time.

General Illumination Fixtures (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
---------------	--------------------------	-------------------

Good	10-15 Years	No
------	-------------	----

Observations

- General lighting fixtures were being replaced with new LED lamps at the time of our observation.
- Existing raceways/sockets for general lighting fixtures appear in most locations to be original to the building. Existing raceways/sockets may lead to accelerated failure of new LED lamps.

Recommendations

- Carefully monitor failure rate of newly installed LED lamps. If many new LED lamps begin to fail sooner than anticipated by LED lamp manufacturer, consider replacement or retrofit of existing raceways/sockets with linear LED tape.

Production Lighting Fixtures (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	1-5 Years	No

Observations

- Existing production lighting fixtures are in good working condition.
- There are limited location where the installation of new catwalk decks serving variable acoustic array system makes aiming/focusing of existing production lighting fixtures problematic.

Recommendations

- Replace fixed focus incandescent fixtures at locations affected by new catwalk decks for variable acoustic array with new automated LED profile units.

Production Audio/Visual Systems (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-3 Years	No

Observations

- Existing line array speakers/subs are in fair condition, but are leased and not owned by P5.
- Lease agreement mandates equipment be removed and placed on tour by leasing company during summer months. Equipment is prone to damage or abuse during touring that can complicate operations once re-installed.

Recommendations

- Replaced leased line array and subs with new, purchased by P5.

Fixed Audience Seating (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	1 Year	No

Observations

- Existing fixed audience seating has well exceeded its intended life and is in desperate need of replacement.

Recommendations

- Replace fixed seating units with new of like kind and arrangement.

Historic Interior Finishes (ASCH)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Poor	1 Year	No

Observations

- Existing decorative plasterwork shows signs of aging and in need of restoration.
- Damage to plaster finishes was observed in multiple locations.

Recommendations

- Restoration of historic plaster finishes by a qualified entity, specializing in historic preservation/restoration is recommended.

End of Arlene Schintzer Concert Hall Observations & Recommendations

Keller Auditorium – Observations & Recommendations

Stage Flooring Systems (Keller)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	End of Life	No

Observations

- Existing stage floor is in very poor condition and in need of replacement.

Recommendations

- Replace existing stage floor with field constructed sprung wood stage floor assembly.

Manual & Motorized Stage Rigging Systems (Keller)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	End of Life (Chain Hoists)	No

Observations

- Existing manual counterweight rigging components have exceeded the manufacturer's recommended life but all line sets appear to be in good operational condition.
- Users indicate a preference to repair damaged/broken manual counterweight components as required, rather than wholesale replacement of stage rigging system.
- Chain hoists at grid iron are obsolete, and servicing is becoming problematic due to lack of manufacturer's direct support.

Recommendations

- Continue to monitor and repair existing manual stage rigging components as required, with Level 2 Stage Rigging Inspections by qualified personnel per current ESTA/ANSI standards annually. Anticipate replacement being required within 5-10 years.
- Replace existing chain motor hoist units with new, matching existing configuration and rating.

Decorative, & Variable Acoustic Draperies (Keller)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Good	5-10 Years	No

Observations

- Draperies deployed during observation appear to be from 2013 and are in surprisingly good condition given their age.

Recommendations

- Clean as required.

Motorized Orchestra Pit (Keller)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	End of Life	No

Observations

- The orchestra pit lift has exceeded its reasonable service life and presents potential safety risks.

Recommendations

- Replace Orchestra Pit Lift with new.

Theatrical Lighting Controls (Keller)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Poor	1 Year	No

Observations

- Existing house and production lighting controls system has reached end of life and is soon to reach end of manufacturer's support period.
- Dedicated DMX/RDM & Production Lighting Network distribution is lacking for a modern flagship performing arts facility.

Recommendations

- Replace existing architectural lighting system with new.
- Provide new dedicated DMX/RDM and Lighting Network distribution backbone on stage, in common control locations, and at all FOH lighting positions.

General Illumination Fixtures (Keller)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-5 Years	No

Observations

- General house lighting fixtures consist of incandescent production lighting fixtures configured as architectural fixtures.
- Lamps for existing fixtures of theatrical grade quality and performance are likely to become problematic to source within the next 1-5 years.

Recommendations

- Replace existing incandescent fixtures with new LED units. Replacement of existing house lighting fixtures with new LED units should be performed at the same time as replacement of existing theatrical lighting controls system.

Production Lighting Fixtures (Keller)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Fair	1-5 Years	No

Observations

- Existing production lighting fixtures are in good working condition, but incandescent units are becoming obsolete, with quality lamps likely becoming hard to source within the next 1-5 years.

Recommendations

- Replace incandescent production lighting fixtures with LED units.

Production Audio/Visual Systems (Keller)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	End of Life	No

Observations

- Existing PA speakers are underpowered and do not provide adequate coverage throughout the space for most performances.

Recommendations

- Replace existing FOH PA system with new.

Fixed Audience Seating (Keller)

Summary Overview

System Rating	Estimated Remaining Life	Life Safety Issue
Very Poor	1 Year	No

Observations

- Existing fixed audience seating has well exceeded intended life and is in desperate need of replacement.

Recommendations

- Replace fixed seating units with new of like kind and arrangement.

Technical Access and Other Life Safety Items (Keller)

Observations

- Elevated Lighting positions lack railings and fall arrest safety systems conforming to current OSHA requirements.

Recommendations

- Provide fall arrest and recovery system at all elevated lighting positions.

End of Keller Auditorium Observations & Recommendations

Respectfully Submitted,

PLA Designs, Inc.

Chris Ochocki, ASTC

Senior Theater Consultant

Appendix B

Metro's Asset Classification Hierarchy				ASTM UniFormat II (2024)	
Level 1	Level 2	Level 3	Level 4	UniFormat Code #	UniFormat 2024 - Level 4 Category
A Substructure	A1 Foundation	A11 Standard Foundation	A1111 Wall Foundations	A101001	WALL FOUNDATIONS
			A1112 Column Foundations & Pile Caps	A101002	COLUMN FOUNDATIONS AND PILE CAPS
			A1113 Perimeter Drainage & Insulation	A101003	DEWATERING
		A12 Special Foundations	A1221 Pile Foundations	A102001	PILE FOUNDATIONS
			A1222 Grade Beams		
			A1223 Caissons	A102002	CAISSONS
			A1224 Underpinning	A102003	UNDERPINNING
			A1225 Dewatering	A102004	DEWATERING
			A1226 Raft Foundations	A102005	RAFT FOUNDATIONS
			A1227 Pressure Injected Grouting	A102006	PRESSURE INJECTED GROUTING
			A1229 Other Special Conditions	A102099	OTHER SPECIAL FOUNDATIONS
		A13 Slab on Grade	A1331 Standard Slab on Grade	A103001	STANDARD SLAB ON GRADE
			A1332 Structural Slab on Grade	A103002	STRUCTURAL SLAB ON GRADE
			A1333 Inclined Slab on Grade	A103003	INCLINED SLAB ON GRADE
			A1334 Trenches, Pits and Bases		
			A1335 Under-Slab Drainage & Insulation	A103006	FOUNDATION DRAINAGE
	A2 Basement Construction	A21 Basement Excavation	A2111 Excavation for Basements	A201001	EXCAVATION FOR BASEMENTS
			A2112 Structure Back Fill & Compaction	A201002	STRUCTURE BACKFILL AND COMPACTION
			A2113 Shoring	A201003	SHORING
		A22 Basement Walls	A2221 Basement Wall Construction	A202001	BASEMENT WALL CONSTRUCTION
			A2222 Moisture Protection	A202002	MOISTURE PROTECTION
			A2223 Basement Wall Insulation	A202003	BASEMENT WALL INSULATION
			A2224 Interior Skin	A202099	OTHER BASEMENT WALLS
B Shell	B1 Superstructure	B11 Floor Construction	B1111 Suspended Basement Floors Construction		
			B1112 Upper Floors Construction		
			B1113 Balcony Floors Construction	B101004	BALCONY CONSTRUCTION
			B1114 Ramps	B101005	RAMPS
			B1115 Exterior Stairs and Fire Escapes		
			B1116 Floor Raceway System		
			B1117 Other Floor Construction	B101099	OTHER FLOOR CONSTRUCTION
		B12 Roof Construction	B1221 Flat Roof Construction		
			B1222 Pitched Roof Construction		
			B1223 Canopies	B102004	CANOPIES
			B1229 Other Roof Systems	B102099	OTHER ROOF CONSTRUCTION
	B2 Exterior Enclosures	B21 Exterior Walls	B2111 Exterior Wall Construction		
			B2112 Parapets	B201004	PARAPETS
			B2113 Exterior Louvers, Screens and Fencing	B201005	EXTERIOR LOUVERS AND SCREENS
			B2114 Exterior Sun Control Devices	B201006	SUN CONTROL DEVICES (EXTERIOR)
			B2115 Balcony Walls & Handrails	B201007	BALCONY WALLS AND RAILINGS
			B2116 Exterior Soffits	B201008	EXTERIOR SOFFITS
		B22 Exterior Windows	B2221 Exterior Windows	B202001	WINDOWS
			B2222 Exterior Curtain Walls	B202003	CURTAIN WALLS
			B2223 Exterior Storefronts	B202004	EXTERIOR GLAZING
		B23 Exterior Doors	B2331 Exterior Glazed Doors & Entrances	B203002	GLAZED DOORS
			B2332 Solid Exterior Doors	B203001	SOLID DOORS
			B2333 Exterior Revolving Doors	B203003	REVOLVING DOORS
			B2334 Exterior Overhead Doors	B203004	OVERHEAD AND ROLL-UP DOORS
			B2339 Other Exterior Doors & Entrances	B203098	OTHER EXTERIOR SPECIALTY DOORS
	B3 Roofing	B31 Roof Coverings	B3111 Roof Finishes		
			B3112 Traffic, Toppings & Paving Membranes		
			B3113 Roof Insulation & Fill	B301003	ROOF INSULATION AND FILL
			B3114 Flashings & Trim	B301004	FLASHINGS AND TRIM
			B3115 Roof Eaves and Soffits		
			B3116 Gutters and Downspouts	B301005	GUTTERS AND DOWNSPOUTS
		B32 Roof Openings	B3221 Glazed Roof Openings		
			B3222 Roof Hatches		
C Interiors	C1 Interior Construction	C11 Partitions	C1111 Fixed partitions	C101001	FIXED PARTITIONS
			C1112 Demountable Partitions	C101002	DEMOUNTABLE PARTITIONS
			C1113 Retractable Partitions	C101003	RETRACTABLE PARTITIONS
			C1114 Site Built Toilet Partitions		
			C1115 Site Built Compartments Cubicles		
			C1116 Interior Balustrades and Screens	C101004	INTERIOR GUARDRAILS AND SCREENS
			C1117 Interior Windows & Storefronts		
		C12 Interior Doors	C1221 Interior Doors		
			C1222 Interior Door Frames		
			C1223 Interior Door Hardware	C102007	INTERIOR DOOR HARDWARE
			C1224 Interior Door Wall Opening Elements		
			C1225 Interior Door Sidelights & Transoms		
			C1226 Interior Hatches & Access Doors		
			C1227 Interior Door Painting & Decorations		
			C1228 Interior Overhead Doors	C102005	INTERIOR OVERHEAD DOORS

Appendix B

Metro's Asset Classification Hierarchy				ASTM UniFormat II (2024)	
Level 1	Level 2	Level 3	Level 4	UniFormat Code #	UniFormat 2024 - Level 4 Category
C Interiors (continued)		C13 Fittings	C1331 Fabricated Toilet partitions		
			C1332 Fabricated Compartments & Cubicles		
			C1333 Storage Shelving and Lockers		
			C1334 Ornamental Metals and Handrails		
			C1335 Identifying Devices		
			C1336 Closet Specialties	C103010	CLOSETS
			C1337 General Fittings & Misc. Metals		
	C2 Stairs	C21 Stair Construction	C2111 Regular Stairs	C201001	INTERIOR STAIR CONSTRUCTION
			C2112 Curved Stairs		
			C2113 Spiral Stairs		
			C2114 Stair Handrails and Balustrades		
			C2115 Fixed Ladders		
		C22 Stair Finishes	C2221 Stair, Tread and Landing Finishes	C202001	INTERIOR STAIR FINISH
			C2222 Stair Soffit Finishes		
			C2223 Stair Handrail & Balustrade Finishes		
	C3 Interior Finishes	C31 Wall Finishes	C3111 Wall Finishes to Inside Exterior Walls		
			C3112 Wall Finishes to Interior Walls		
			C3113 Column Finishes		
		C32 Floor Finishes	C3221 Floor Toppings		
			C3222 Traffic Membranes		
			C3223 Hardeners and Sealers	C302010	HARDENERS AND SEALERS
			C3224 Flooring		
			C3225 Carpeting	C302005	CARPETING
			C3226 Bases, Curbs and Trim		
			C3227 Access Pedestal Flooring		
		C33 Ceiling Finishes	C3331 Ceiling Finishes		
			C3332 Suspended Ceilings	C303007	SUSPENSIONS SYSTEMS
			C3333 Other Ceilings	C303099	OTHER CEILING AND CEILING FINISHES
D Services	D1 Conveying	D11 Elevators & Lifts	D1111 Passenger Elevators	D101002	PASSENGER ELEVATORS
			D1112 Freight Elevators	D101003	FREIGHT ELEVATORS
			D1113 Lifts		
		D12 Escalators & Moving Walks	D1221 Escalators		
			D1222 Moving Walks	D102002	MOVING WALKS
		D19 Other Conveying Systems	D1991 Dumbwaiters		
			D1992 Pneumatic Tube Systems	D109001	PNEUMATIC TUBE SYSTEMS
			D1993 Hoists & Cranes		
			D1994 Conveyors	D109002	CONVEYORS
			D1995 Chutes		
			D1996 Turntables	D109004	TURNTABLES
			D1997 Baggage Handling & Loading Systems		
			D1998 Transportation Systems	D109006	TRANSPORTATION SYSTEMS
	D2 Plumbing	D21 Plumbing Fixtures	D2111 Water Closets	D201001	WATERCLOSETS
			D2112 Urinals	D201002	URINALS
			D2113 Lavatories	D201003	LAVATORIES
			D2114 Sinks	D201004	SINKS
			D2115 Bathtubs		
			D2116 Water Fountains		
			D2117 Showers		
			D2118 Drinking Fountains and Coolers	D201006	DRINKING FOUNTAINS AND COOLERS
			D2119 Bidets and Other Plumbing Fixtures	D201007	BIDETS
			D2120 Water Heaters		
		D22 Domestic Water Distribution	D2221 Cold Water Service		
			D2222 Hot Water Service		
			D2223 Domestic Water Supply Equipment		
		D23 Sanitary Water	D2331 Waste Piping	D203001	WASTE PIPE AND FITTINGS
			D2332 Vent Piping	D203002	VENT PIPE AND FITTINGS
			D2333 Floor Drains	D203003	FLOOR DRAINS
			D2334 Sanitary Waste Equipment	D203004	SANITARY AND VENT EQUIPMENT
			D2335 Pipe Insulation		
		D24 Rain Water Drainage	D2441 Pipe & Fittings	D204001	PIPE AND FITTINGS
			D2442 Roof Drains	D204002	ROOF DRAINS
			D2443 Rainwater Drainage Equipment	D204003	RAINWATER DRAINAGE EQUIPMENT
			D2444 Pipe Insulation		
		D29 Other Plumbing Systems	D2991 Gas Distribution		
			D2992 Acid Waste Systems	D209002	ACID WASTE SYSTEMS
			D2993 Interceptors	D209003	INTERCEPTORS
			D2994 Pool Piping and Equipment	D209004	POOL PIPING AND EQUIPMENT
			D2995 Decorative Fountain Piping Devices		
			D2999 Other Piping Systems		

Appendix B

Metro's Asset Classification Hierarchy				ASTM UniFormat II (2024)	
Level 1	Level 2	Level 3	Level 4	UniFormat Code #	UniFormat 2024 - Level 4 Category
	D3 HVAC	D31 Energy supply	D3111 Oil Supply System	D301001	OIL SUPPLY SYSTEM
			D3112 Gas Supply system	D301002	GAS SUPPLY SYSTEM
			D3113 Coal Supply System	D301003	COAL SUPPLY SYSTEM
			D3114 Steam Supply System	D301004	STEAM SUPPLY SYSTEM (FROM CENTRAL PLANT)
			D3115 Hot Water Supply System	D301005	HOT WATER SUPPLY SYSTEM (FROM CENTRAL PLANT)
			D3116 Solar Energy System	D301006	SOLAR ENERGY SUPPLY SYSTEMS
			D3117 Wind Energy System	D301007	WIND ENERGY SUPPLY SYSTEM
		D32 Heat Generating Systems	D3221 Boilers		
			D3222 Boiler Room Piping & Specialties		
			D3223 Auxiliary Equipment	D302005	AUXILIARY EQUIPMENT
		D33 Cooling Generating Systems	D3224 Insulation	D302006	EQUIPMENT THERMAL INSULATION
			D3331 Chilled Water Systems	D303001	CHILLED WATER SYSTEMS
			D3332 Direct Expansion Systems	D303002	DIRECT EXPANSION SYSTEMS
		D34 Distribution Systems	D3441 Air Distribution Systems	D304001	AIR DISTRIBUTION, HEATING, AND COOLING
			D3442 Exhaust Ventilation Systems	D304007	EXHAUST SYSTEMS
			D3443 Steam Distribution Systems	D304002	STEAM DISTRIBUTION SYSTEMS
			D3444 Hot Water Distribution	D304003	HOT WATER DISTRIBUTION SYSTEMS
			D3445 Chilled Water Distribution	D304006	CHILLED WATER DISTRIBUTION SYSTEMS
			D3446 Change-over Distribution system	D304004	CHANGE OVER DISTRIBUTION SYSTEMS
			D3447 Glycol Distribution Systems	D304005	GLYCOL DISTRIBUTION SYSTEMS
		D35 Terminal & Package Units	D3551 Terminal Self-Contained Units		
			D3552 Package Units	D305006	PACKAGE UNITS
		D36 Controls & Instrumentation	D3661 Heating Generating Systems		
			D3662 Cooling Generating Systems		
			D3663 Heating-Cooling Air Handling Units		
			D3664 Exhaust & Ventilating Systems		
			D3665 Hoods and Exhaust Systems		
			D3666 Terminal Devices		
			D3667 General Monitoring & Control		
			D3668 Building Automation Systems		
		D37 Systems Testing & Balancing	D3669 Other Controls and Instrumentation	D306099	OTHER CONTROLS INSTRUMENTATION
			D3771 Piping System Testing & Balancing		
			D3772 Air systems Testing & Balancing	D307002	AIR SIDE TESTING AND BALANCING—HEATING, COOLING, AND EXHAUST
			D3773 HVAC Commissioning	D307003	HVAC COMMISSIONING
			D3779 Other Systems Testing and Balancing	D307099	OTHER SYSTEMS TESTING AND BALANCING
		D39 Other HVAC Systems & Controls	D3991 Special Cooling Systems & Devices		
			D3992 Special Humidity Control		
			D3993 Dust & Fume Collectors		
			D3994 Air Curtains		
			D3995 Air Purifiers		
			D3996 Paint Spray Booth Ventilation		
			D3997 General Construction Items (HVAC)		
		D41 Fire Protection	D4111 Sprinkler Water Supply		
			D4112 Sprinkler Pumping Equipment		
			D4113 Dry Sprinkler System		
			D4114 Wet Sprinkler Systems		
		D42 Standpipes	D4221 Standpipe Water Supply		
			D4222 Pumping Equipment		
			D4223 Standpipe Equipment		
			D4224 Fire Hose Equipment		
		D43 Fire Protection Specialties	D4331 Fire Extinguishers		
			D4332 Fire Extinguisher Cabinets		
		D49 Other Fire Protection Systems	D4991 Carbon Dioxide Systems	D409001	CARBON DIOXIDE SYSTEMS
			D4992 Foam Generating Equipment	D409002	FOAM GENERATING EQUIPMENT
			D4993 Clean Agent Systems	D409003	CLEAN AGENT SYSTEMS
			D4994 Dry Chemical System		
			D4995 Hood & Duct Fire Protection	D409005	HOOD AND DUCT FIRE PROTECTION
	D5 Electrical	D51 Electrical Service & Distribution	D5111 High Tension Service & Dist.		
			D5112 Low Tension Service & Dist.		
		D52 Lighting & Branch Wiring	D5221 Branch Wiring Devices	D502001	BRANCH WIRING
			D5222 Lighting Equipment	D502002	LIGHTING EQUIPMENT
			D5223 Lighting Controls		
		D53 Communications & Security	D5331 Public Address & Music Systems	D503004	PUBLIC ADDRESS SYSTEMS
			D5332 Intercommunication & Paging System	D503005	INTERCOMMUNICATIONS SYSTEMS - Intercom and Paging system
			D5333 Telephone System		
			D5334 Call Systems		
			D5335 Television Systems	D503007	TELEVISION SYSTEMS - Video management and Recording System
			D5336 Clock and Program systems	D503006	CLOCK AND PROGRAM SYSTEMS

Appendix B

Metro's Asset Classification Hierarchy				ASTM UniFormat II (2024)	
Level 1	Level 2	Level 3	Level 4	UniFormat Code #	UniFormat 2024 - Level 4 Category
E Equipment & Furnishin	E1 Equipment	D59 Other Electrical System	D5337 Fire Alarm systems		
			D5338 Security and Detection Systems		
			D5339 Local Area Networks		
			D5991 Grounding Systems	D509003	GROUNDING SYSTEMS
			D5992 Emergency Light & Power Systems		
			D5993 Floor Raceway Systems		
			D5994 Other Special Systems & Devices	D509099	OTHER SPECIAL SYSTEMS AND DEVICES
			D5995 General Construction Items (Elect.)		
		E11 Commercial Equipment	E1111 Security & Vault Equipment	E101005	SECURITY AND VAULT EQUIPMENT
			E1112 Teller and Service Equipment	E101006	TELLER AND SERVICE EQUIPMENT
			E1113 Registration Equipment		
			E1114 Checkroom Equipment		
			E1115 Mercantile Equipment	E101007	MERCANTILE EQUIPMENT
			E1116 Laundry & Dry Cleaning Equipment		
			E1117 Vending Equipment		
			E1118 Office Equipment		
		E12 Institutional Equipment	E1221 Ecclesiastical Equipment	E102007	ECCLESIASTICAL EQUIPMENT
			E1222 Library Equipment	E102006	LIBRARY EQUIPMENT
			E1223 Theater & Stage Equipment		
			E1224 Instrumental Equipment	E102008	INSTRUMENTAL EQUIPMENT
			E1225 Audio-visual Equipment	E102009	AUDIO-VISUAL EQUIPMENT
			E1226 Detention Equipment	E102010	DETENTION EQUIPMENT
			E1227 Laboratory Equipment	E102003	LABORATORY EQUIPMENT
			E1228 Medical Equipment	E102002	MEDICAL EQUIPMENT
			E1229 Other Institutional Equipment		
		E13 Vehicular Equipment	E1331 Vehicular Service Equipment		
			E1332 Parking Control Equipment	E103001	PARKING CONTROL EQUIPMENT
			E1333 Loading Dock Equipment	E103002	LOADING DOCK EQUIPMENT
			E1339 Other Vehicular Equipment		
		E19 Other Equipment	E1991 Maintenance Equipment	E109001	BUILT-IN MAINTENANCE EQUIPMENT
			E1992 Solid Waste Handling Equipment	E109003	WASTE HANDLING EQUIPMENT
			E1993 Food Service Equipment	E109002	FOOD SERVICE EQUIPMENT
			E1994 Residential Equipment	E109004	RESIDENTIAL EQUIPMENT
			E1995 Unit Kitchens	E109005	UNIT KITCHENS
			E1997 Window Washing Equipment		
			E1998 Radios		
			E1999 Other Equipment		

Appendix B

Metro's Asset Classification Hierarchy				ASTM UniFormat II (2024)	
Level 1	Level 2	Level 3	Level 4	UniFormat Code #	UniFormat 2024 - Level 4 Category
F Special Construction &	E2 Furnishings	E21 Fixed Furnishings	E2111 Fixed Artwork	E201001	FIXED ARTWORK
			E2112 Fixed Casework		
			E2113 Blinds and Other Window Treatment		
			E2114 Fixed Floor Grilles and Mats		
			E2115 Fixed Multiple Seating		
			E2116 Fixed Interior Landscaping	E201005	FIXED INTERIOR LANDSCAPING
		E22 Movable Furnishings	E2221 Movable Artwork	E202001	MOVEABLE ART WORK
			E2222 Furniture & Accessories		
			E2223 Movable Rugs and Mats	E202004	RUGS AND ACCESSORIES
			E2224 Movable Interior Landscaping		
	F1 Special Construction	F11 Special Structures	F1111 Air Supported Structures	F101003	AIR-SUPPORTED STRUCTURES
			F1112 Pre-engineered Structures		
			F1113 Other Special Structures	F101099	OTHER SPECIAL CONSTRUCTION
		F12 Integrated Construction	F1221 integrated Assemblies		
			F1222 Special Purpose Rooms	F102001	SPECIAL PURPOSE ROOMS
			F1223 Other Integrated Construction	F102099	OTHER INTEGRATED CONSTRUCTION
		F13 Special Construction Systems	F1331 Sound, Vibration & Seismic Const.		
			F1332 Radiation Protection	F103003	RADIATION PROTECTION
			F1333 Special Security Systems		
			F1334 Vaults	F103001	VAULTS
			F1339 Other Special Construction Systems	F103099	OTHER SPECIAL CONSTRUCTION SYSTEMS
		F14 Special Facilities	F1441 Aquatic Facilities	F104001	INTERIOR SWIMMING POOLS
			F1442 Ice Rinks	F104005	ICE RINKS
			F1443 Site Constructed Incinerators		
			F1444 Kennels & Animal Shelters	F104003	KENNELS AND ANIMAL SHELTERS
			F1445 Liquid & Gas Storage Tanks	F104002	LIQUID AND GAS STORAGE TANKS
			F1449 Other Special Facilities	F104099	OTHER SPECIAL FACILITIES
		F15 Special Controls & Instrumentation	F1551 Recording Instrumentation	F105001	RECORDING INSTRUMENTATION
			F1552 Building Automation System	F105001	RECORDING INSTRUMENTATION
			F1559 Other Special Controls & Instrumentation	F105099	OTHER SPECIAL CONTROLS AND INSTRUMENTATION
	F2 Selective Building Demolition	F21 Building Elements Demolition	F2111 Building Interior Demolition		
			F2112 Building Exterior Demolition		
		F22 Hazardous Components	F2221 Removal of Hazardous Components		
			F2222 Encapsulation of Hazardous Components		
G Building Sitework	G1 Site Preparation	G11 Site Clearing	G1111 Clearing & Grubbing		
			G1112 Tree Removal & Thinning		
		G12 Site Demolition & Relocation	G1221 Building Demolition	G102001	BUILDING MASS DEMOLITION
			G1222 Demolition of Site Components	G102002	ABOVE GROUND SITE DEMOLITION
			G1223 Relocation of Building & Utilities		
			G1224 Utilities Relocation	G102005	UTILITY RELOCATION
		G13 Site Earthwork	G1331 Site Grading Excavation		
			G1332 Borrow Fill	G103004	FILL AND BORROW
			G1333 Soil Stabilization & Treatment		
			G1334 Site Dewatering		
			G1335 Site Shoring	G103009	SHORING
			G1336 Embankments		
			G1337 Erosion Control	G103011	TEMPORARY EROSION AND SEDIMENT CONTROL
		G14 Hazardous Waste Remediation	G1441 Removal of Contaminated Soil	G104001	REMOVAL OF CONTAMINATED SOIL
			G1442 Soil Restoration & Treatment	G104002	SOIL RESTORATION AND TREATMENT
	G2 Site Improvements	G21 Roadways	G2111 Bases and Sub-Bases	G201001	BASES AND SUBBASES
			G2112 Paving & Surfacing	G201003	PAVED SURFACES
			G2113 Curbs, Gutters and Drains		
			G2114 Guardrails and Barriers	G201005	GUARDRAILS AND BARRIERS
			G2115 Painted Lines		
			G2116 Markings & Signage		
			G2117 Vehicular Bridges		
			G2221 Bases and Sub-Bases	G202001	BASES AND SUBBASES
		G22 Parking Lots	G2222 Paving & Surfacing		
			G2223 Curbs, Rails & Barriers	G202003	PAVED SURFACES
			G2224 Parking Booths & Equipment		
			G2225 Markings & Signage	G202004	MARKING AND SIGNAGE
		G23 Pedestrian Paving	G2331 Paving & Surfacing		
			G2332 Edging		
			G2333 Exterior Steps		
		G24 Site Development	G2334 Pedestrian Bridges		
			G2244 Signage		
			G2441 Fences & Gates	G204001	FENCING AND GATES
			G2442 Retaining Walls	G204002	RETAINING WALLS
			G2443 Terrace & perimeter Walls		
			G2444 Signage	G204005	SIGNAGE
			G2445 Site Furnishings		

Appendix B

Metro's Asset Classification Hierarchy				ASTM UniFormat II (2024)	
Level 1	Level 2	Level 3	Level 4	UniFormat Code #	UniFormat 2024 - Level 4 Category
			G2446 Fountains, Pools & Watercourses		
			G2447 Playing Fields	G204007	PLAYING FIELDS
			G2448 Flagpoles	G204009	FLAGPOLES
			G2449 Miscellaneous Structures		
		G25 Landscaping	G2551 Fine Grading & Soil Preparation	G205001	FINE GRADING AND SOIL PREPARATION
			G2552 Erosion Control Measures	G205002	EROSION CONTROL MEASURES
			G2553 Top Soil & Planting Beds	G205003	TOPSOIL AND PLANTING BEDS
			G2554 Seeding & Sodding	G205004	SEEDING, SPRIGGING, AND SODDING
			G2555 Planting	G205005	PLANTINGS
			G2556 Planters	G205006	PLANTERS
			G2557 Irrigation Systems	G205007	IRRIGATION SYSTEMS
			G2558 Other Landscape Features	G205099	OTHER LANDSCAPING
			G2559 Trees		
	G3 Site Mechanical Util	G31 Water Supply	G3111 Potable Water Distribution & Storage		
			G3112 Non-Potable Water Distribution & Storage		
			G3113 Well Systems	G301001	WELL SYSTEMS
			G3114 Fire Protection Distribution & Storage		
			G3115 Pumping Stations	G301007	PUMPING STATIONS
			G3116 Package Water Treatment Plants	G301008	PACKAGED WATER TREATMENT PLANTS
		G32 Sanitary Sewer	G3221 Piping	G302001	SANITARY SEWER PIPING
			G3222 Manholes & Cleanouts	G302002	SANITARY SEWER MANHOLES AND CLEANOUTS
			G3223 Septic Disposal Systems		
			G3224 Lift Stations	G302003	LIFT STATIONS AND PUMPING STATIONS
			G3225 Packaged Water Waste Treatment Plants	G302004	PACKAGED SANITARY SEWER TREATMENT PLANTS
			G3226 Septic tanks	G302005	SEPTIC TANKS
			G3227 Drain Fields	G302006	DRAIN FIELDS
		G33 Storm Sewer	G3331 Piping	G303001	STORM SEWER PIPING
			G3332 Manholes		
			G3333 Headwalls & Catch Basins		
			G3334 Lift Stations	G303003	LIFT STATIONS
			G3335 Retention Ponds		
			G3336 Ditches & Culverts	G303004	CULVERTS
		G34 Heating Distribution	G3441 Steam Supply		
			G3442 Condensate Return		
			G3443 Hot Water Supply System	G304003	UNDERGROUND HOT WATER SYSTEMS
		G35 Cooling Distribution	G3444 Pumping Stations	G304006	PUMPING STATIONS
			G3551 Chilled Water Piping		
			G3552 Wells for Cooling	G305004	WELLS FOR COOLING
			G3553 Pumping Stations	G305005	PUMPING STATIONS
		G36 Fuel Distribution	G3554 Cooling Towers on Site	G305006	ON-SITE COOLING TOWERS
			G3661 Fuel Piping	G306001	LIQUID FUEL DISTRIBUTION PIPING
			G3662 Fuel Equipment	G306003	LIQUID FUEL DISPENSING EQUIPMENT
			G3663 Fuel Storage Tanks	G306004	LIQUID FUEL STORAGE TANKS
			G3664 Fuel Dispensing Stations		
		G39 Other Site Mechanical Util	G3991 Industrial Waste Systems		
			G3992 Petroleum Oil & Lubricants Dist Systems		
	G4 Site Electrical Utiliti	G41 Electrical Distribution	G4111 Substations	G401001	SUBSTATIONS
			G4112 Overhead Power Distribution	G401004	OVERHEAD ELECTRIC CONDUCTORS
			G4113 Underground Power Distribution	G401006	UNDERGROUND ELECTRIC CONDUCTORS
		G42 Site Lighting	G4221 Fixtures & Transformers		
			G4222 Poles		
			G4223 Wiring & Conduits & Ductbanks		
			G4224 Site Lighting Controls		
		G43 Site Communications & Security	G4331 Site Communications Systems	G403001	TELECOMMUNICATIONS SYSTEMS
			G4332 Site Security & Alarm Systems		
		G49 Other Site Electrical Util	G4991 Cathodic Protection		
			G4992 Site Emergency Power Generation		
	G9 Other Site Construc	G91 Service and Pedestrian	G9111 Service Tunnels	G901001	CONSTRUCTION OF SERVICE AND PEDESTRIAN TUNNELS
			G9112 Trench Boxes		
			G9113 Pedestrian Tunnels	G901002	PREFABRICATED SERVICE AND PEDESTRIAN TUNNELS
		G99 Other Site Systems & E	G9991 Snow Melting Systems		